




February 23, 2002

Carol Long/ Barclay School Supplies
166 Livingston Street
Brooklyn, NY 11201-5811

Joel A. Miele Sr., P.E.
Commissioner

Robert C. Avaltroni
Deputy Commissioner

Bureau of
Environmental Compliance
Tel (718) 595-4418
Fax (718) 595-4422

Subject: 24 WARREN STREET
26 Warren St
Second Notice

Dear Sir/ Madam:

This is a follow-up to the NYC DEP request for copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. To date, our office has not received the requested documents and information. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

A handwritten signature in black ink, appearing to read "R. Radhakrishnan".

R. Radhakrishnan, P.E.

Director

Asbestos Control Program



(718) DEP-HELP

WTC Visual Survey Form

Premise Address: 24 WARREN ST.

Block: 135 **Residential** ☐ **Commercial** ☐ **Name of Building:** _____
Lot: 11 **Mix Use** ☐ **Other** ☐

of Stories: 5 **AKA's:** 24-26 Warren St.

Building Owner/Management: _____ **Telephone Number:** () _____
Name: _____ **FAX:** () _____
Address: _____

On Site Contact: _____ **Telephone Number:** () _____
Name: _____

Building Owner Management Activities
Interior Survey Performed ☐ Yes ☐ No
Exterior Survey Performed ☐ Yes ☐ No
General Clean Up ☐ Yes ☐ No **Locations:** _____
ACM Clean Up ☐ Yes ☐ No **Locations:** _____
Air Monitoring ☐ Yes ☐ No **Locations:** _____

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description:
Cinderblock ^{brickwork} ^{etc.} on south facade, layer above security fence roll down - fire escape

Roof

Debris: ☐ No Visible /Fine Layer ^{light dust} ☒ ½ to 1" ^{1 dust} ☐ > 1" ^{1 dust}

Description: In settled areas fine layer th
No roof cleaning

Setbacks ☐ N/A

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments
Visible debris at base of roll down gate for tenant 1st fl commercial
building appears vacant

Date: 1/27/2002Inspection Team: Name: Bob FitzpatrickAgency: USEPAName: Pennig TheodorallyAgency: NYC DEP

RFI