

WTC Visual Survey Form

Premise Address: <u>77 Warren Street</u>		
Block: <u>132</u>	Residential ☐ Commercial ☐	Name of Building:
Lot: <u>23</u>	Mix Use ☐ Other ☐	
# of Stories: <u>5</u>	AKA's:	
Building Owner/Management: <u>Tony Century Realty</u>		Telephone Number: (212) <u>267-7778</u>
Name:		FAX: ()
Address:		
On Site Contact:		
Name: <u>Tenant</u>		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description:

Two types of facade - old brownstone & an overlay on 2nd fl.
fine layer of dust observed.

Roof

Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"

Description: _____

Setbacks

Floor:	Debris:		
_____	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
_____	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
_____	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
_____	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
_____	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

DOB permit posted for commercial space - no access

Date: 1/28 /2002

Inspection Team: Name: Perry Theodore Kellys

Agency: NYC DEP

Name: Horton Hendrick

Agency: NYSDOL

