

WTC Visual Survey Form

Premise Address: 69 WARRICK ST		
Block: 132 Lot: 30	Residential ☐ Commercial ☐ Mix Use ☐ Other ☐ CARPARK	Name of Building: ALPACI
# of Stories:	AKA's:	
Building Owner/Management: Name: 69 WARRICK ST PARKING LOT		Telephone Number: () 233 5688 FAX: ()
Address:		
On Site Contact: Name: CSIBETI ROMANA		Telephone Number: PII
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☒ No		
Exterior Survey Performed ☐ Yes ☒ No		
General Clean Up ☒ Yes ☐ No Locations: CARPARK CARPARK STAIRS		
ACM Clean Up ☐ Yes ☒ No Locations:		
Air Monitoring ☐ Yes ☒ No Locations:		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	Debris	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"	
East	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"	
West	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"	
Facade Description: OPEN LOT POWER WASHING OF FACADE OF NORTH					
Roof N/A					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description:					
Setbacks N/A ☒					
Floor:		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor:		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor:		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor:		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor:		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Comments SUNSHINE NEXT DOOR SIGNAGE ASSET SUNSHINE ON GRASS UNDER CAR RACKS 136 CHURCH ST / 37 WARRICK ST SAME ADDRESS					

Date: 01/25/2002

Inspection Team: Name: HENRIK

Agency: DEC

Name: PENNY

Agency: DEP

WTC Visual Survey Form

Premise Address: <u>69 Warren St</u>		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	☐ Yes ☐ No	Debris	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
Facade Description: _____					

Roof					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: _____					

Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					
<u>The entire parking lot is cleaned.</u>					

Date: 2/27/2002

Inspection by: Name: AL

Agency: _____
Agency: _____