

WTC Visual Survey Form



Premise Address: 68 Warren St.		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☒ Parking ☐ Open lot	
# of Stories: 1	AKA's:	
Building Owner/Management:		Telephone Number: (212) 233-6867
Name: B. Daffe Real Estate Co.		FAX: (212) 233-7930
Address: 68 West Broadway		
On Site Contact:		Telephone Number: (212) 233-6867
Name: Sept Rudy		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☒ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: _____

Roof

Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"

Description: N/A

Setbacks

N/A ☒

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Parking lot - cleaned by United Restoration
at 74, 88 West Broadway & 72-74 Warren St

Date: 1/25/2002

Inspection Team: Name:

Penny Theodorellus

Agency: NYCDOP

Name:

Horton Hendrick

Agency: NYSDOL

Sharon Sachs (212) 645-2324
84 West Broadway

Mark Jaffe - bldg manager
(212) 839-7000
→ for testing



TEST BUILDING



Investigator



Insurance

Go Clean to

United Restoration




HEPA cleaned
NAM.

> 3 wks cleaning



Applied.



REMCO

cleaned outside & roof.

4N