

WTC Visual Survey Form

Premise Address: 51 Warren St.		
Block: 133 Lot: 22	Residential ☐ Commercial ☐ Mix Use ☐ Other ☐	Name of Building:
# of Stories: 6	AKA's: 49-51 Warren St.	
Building Owner/Management: Name: ASSA		Telephone Number: (718) 459-6644 FAX: ()
Address:		
On Site Contact: Name: Telephone Number: ()		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☒ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: Side walk shed on North Facade blocked view.					
Roof					
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description: Not complete layer - in areas roof does not appear to have been cleaned - inspected from gaining access to adjacent roof					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Comments					

Date: 1/25/2002

Inspection Team: Name: Hector Hendrick

Agency: MSDOL

Name: Penny Theodorely

Agency: NYC DEP



Date: 1/30/ 2 Time: 08:30:26 AM