

**ASBESTOS CONTROL PROGRAM
EMERGENCY RESPONSE
D I A G R A M**

NAME <u>ALFONSO PLUMIE</u> BADGE # <u>A010</u> LOCATION <u>90 WASHINGTON ST NYC</u> <u>ZAR REALTY 52-154 WEST ST</u>	DATE <u>2/27/02</u>
Photographs 4-8 (1)	
ROOF ☒ No Visible Debris ☐ Entire Roof Covered with Debris ☐ Partial Roof Covered ☐ Local/Isolated Areas ☐ Gutters ☐ 25% of the roof ☐ 50% of the roof ☐ 75% of the roof FACADE ☐ Clean ☒ Entire Facade req. Clean-up ☐ _____ Req. Clean-up	