

NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION ASBESTOS INSPECTION REPORT

TOTAL FEET: 7600 0

Basis of Inspection:

FL	SF	LF
RO	0	0

ONLY TYPEWRITTEN
APPLICATIONS WILL BE
ACCEPTED

NOTE: ASBESTOS INSPECTION REPORT SHALL BE SUBMITTED
TO NYC DEP NOT LESS THAN ONE WEEK IN ADVANCE
OF START OF THE WORK (ABATEMENT ACTIVITIES)

FEE EXEMPT: Yes

1. \$0.00

11,809

START DATE: 10/28/2002 COMPLETION DATE: 11/02/2002

I. FACILITY

ADDRESS: 90 Washington Street BORO: MANHATTAN ZIP: _____
TYPE OF FACILITY: _____ BLOCK: _____ LOT: _____

II. BUILDING OWNER

NAME: N/A Zar Realty, Inc.
TEL. #: _____
ADDRESS: N/A N/A N/A N/A CITY: N/A STATE: N/A ZIP: 11368

IV. ASBESTOS ABATEMENT CONTRACTOR

NAME: TRIO ASBESTOS REMOVAL CORP
TEL. #: (718) 961-4100 FEDERAL EMPLOYER IDENTIFICATION #: PII
ADDRESS: 14-20 129TH STREET CITY: COLLEGE POINT STATE: NY ZIP: 11356

V. THIRD PARTY AIR MONITOR

NAME: WARREN & PANZER GROUP
TEL. #: _____
ADDRESS: 228 EAST 45TH STREET CITY: NEW YORK STATE: NY ZIP: 10017

VI. LABORATORY FOR SAMPLE ANALYSIS

NAME: WKP LABORATORIES C/O WARREN & PANZER
NYS ELAP #: 11251

ASBESTOS WORK SCHEDULE ☒ DAY ☒ EVENING ☐ NIGHT ☒ WEEKENDS ☒ WEEKDAYS

INSPECTOR NAME: R. Ramonohan SQUAD #: 1 BADGE #: A078

DATE OF INSPECTION: 10/28/02 - 11/05/02 TIME OF INSPECTION: From: 8 am AM ☒ PM ☐

To: 5 pm AM ☐ PM ☒

Contact at site: Jan Wolkowicz + 5 Handlers, Celestine Obikaw / W&P

Inspection disclosed that the following sections were complied with: (Check all that apply)

☐ 1-51 - Notifications, Reports, Plan	☒ 1-71 - Air Sampling and Monitoring	☒ 1-91 - Worker Protection
☐ 1-101 - Materials and Equipment	☒ 1-116 - Work Place Preparation	☒ 1-117 - Worker Decontamination System
☐ 1-118 - Waste Decontamination System	☐ 1-126 - Engineering Controls	☐ 1-127 - Entry/Exit Procedures
☐ 1-129 - Maintenance of Barriers	☐ 1-138 - Encapsulation	☐ 1-139 - Enclosure
☐ 1-140 - Glovebag	☐ 1-141 - Tent	☒ 1-137 - ACM Disturbance, Removal, Handling
☐ 1-146 - Preliminary Clean-up	☐ 1-147 - Final Clean-up	
☐ Project not started		Inspection

revealed all ACM to be intact. New start date: _____

☐ Project ongoing, expected completion date: _____

☐ Project completed on or about: _____. All surfaces, including abated surfaces are free of visible ACM and encapsulate

☐ Follow up necessary on _____

Samples taken: ☒ No ☐ Yes 1 _____ 2 _____ 3 _____
4 _____ 5 _____ 6 _____ Photos taken: ☐ Yes ☒ No

Additional comments: 10/28/02 MONDAY: Jan Wolkowicz + 7 Handlers constructed a decon unit at 27th floor and began bagging the debris and pebbles on the 13th floor setback. Air sampling was performed.
10/29/02 TUESDAY: Jan Wolkowicz + 6 Handlers cleaning at the east wing of 13th floor setback. Air sampling was performed.
10/30/02 WEDNESDAY: Jan Wolkowicz + 6 Handlers, 13th floor setback. Set back washing completed at 12:30 pm and bag out completed at the end of the day. Air sampling performed.
10/31/02 THURSDAY: Ireneusz Womoczyl + 8 Handlers, began washing the gravel on bulkhead roof. Celestine Obikaw of Warren & Panzer performed air sampling.

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = STATEN ISLAND

RESULT CODES 1 = VIOLATION ISSUED 2 = NO VIOLATION ISSUED 3 = NO ACCESS

4 = PROJECT NOT STARTED (NO NOV) 5 = PROJECT COMPLETED (NO NOV)

RESULT CODE

5

SUPERVISOR INITIALS

RE

NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION

TOTAL FEET: 7600 0

ASBESTOS INSPECTION REPORT Basis of Inspection:

FL	SF	LF
RO	7600	0

ONLY TYPEWRITTEN
APPLICATIONS WILL BE
ACCEPTEDNOTE: ASBESTOS INSPECTION REPORT SHALL BE SUBMITTED
TO NYC DEP NOT LESS THAN ONE WEEK IN ADVANCE
OF START OF THE WORK (ABATEMENT ACTIVITIES)

TRU1787MN02

FEE EXEMPT: Yes

11801

1. \$0.00

START DATE: 6/11/2002 COMPLETION DATE: 7/13/2002

I. FACILITY

ADDRESS: 90 Washington Street. BORO: MANHATTAN ZIP:
TYPE OF FACILITY: BLOCK: LOT:

II. BUILDING OWNER

NAME: N/A
TEL. #:
ADDRESS: N/A N/A N/A N/A CITY: N/A STATE: N/A ZIP: 11368

IV. ASBESTOS ABATEMENT CONTRACTOR

NAME: TRIO ASBESTOS REMOVAL CORP
TEL. #: (718) 961-4100 FEDERAL EMPLOYER IDENTIFICATION #: PII
ADDRESS: 14-20 129TH STREET CITY: COLLEGE POINT STATE: NY ZIP: 11356

V. THIRD PARTY AIR MONITOR

NAME: WARREN & PANZER GROUP
TEL. #:
ADDRESS: 228 EAST 45TH STREET CITY: NEW YORK STATE: NY ZIP: 10017

VI. LABORATORY FOR SAMPLE ANALYSIS

NAME: WKP LABORATORIES C/O WARREN & PANZER
NYS ELAP #: 11251ASBESTOS WORK SCHEDULE ☒ DAY ☒ EVENING ☐ NIGHT ☒ WEEKENDS ☒ WEEKDAYS

INSPECTOR NAME: SQUAD #: BADGE #:

DATE OF INSPECTION: TIME OF INSPECTION: From: AM PM

To: AM PM

Contact at site:

Inspection disclosed that the following sections were complied with: (Check all that apply)

- | | | |
|---|---|---|
| ☐ 1-51 - Notifications, Reports, Plan | ☐ 1-71 - Air Sampling and Monitoring | ☐ 1-91 - Worker Protection |
| ☐ 1-101 - Materials and Equipment | ☐ 1-116 - Work Place Preparation | ☐ 1-117 - Worker Decontamination System |
| ☐ 1-118 - Waste Decontamination System | ☐ 1-126 - Engineering Controls | ☐ 1-127 - Entry/Exit Procedures |
| ☐ 1-129 - Maintenance of Barriers | ☐ 1-138 - Encapsulation | ☐ 1-139 - Enclosure |
| ☐ 1-140 - Glovebag | ☐ 1-141 - Tent | ☐ 1-137 - ACM Disturbance, Removal, Handling |
| ☐ 1-146 - Preliminary Clean-up | ☐ 1-147 - Final Clean-up | |
| ☐ Project not started . Inspection | | |

revealed all ACM to be intact. New start date:

☐ Project ongoing, expected completion date:☐ Project completed on or about: . All surfaces, including abated surfaces are free of visible ACM and encapsulate☐ Follow up necessary onSamples taken: ☐ No ☐ Yes 1 2 3
4 5 6 Photos taken: ☐ Yes ☐ No

Additional comments: 11/01/02 Friday: Ireneusz Womoczyl + 8 Handlers.

Started washing the roof gravel on the main roof. Celestine obika performed air sampling for Warren & Panzer.

11/02/02 Saturday: Ireneusz and crew continue the gravel washing on main roof. Air sampling was conducted by Celestine.

11/03/02 Sunday: Ireneusz & crew continued the roof gravel washing. Air sampling was performed by Celestine obika & Edwin Ellis.

11/04/02 Monday: Ireneusz & crew of 7 handlers continued gravel washing on roof.

11/05/02 Tuesday: Ireneusz & crew gravel washing completed. Bags of waste removed completed.

BORO 1 = MANHATTAN 2 = BRONX 3 = BROOKLYN 4 = QUEENS 5 = STATEN ISLAND

RESULT CODES 1 = VIOLATION ISSUED 2 = NO VIOLATION ISSUED 3 = NO ACCESS

4 = PROJECT NOT STARTED (NO NOV) 5 = PROJECT COMPLETED (NO NOV)

RESULT CODE

5

SUPERVISOR INITIALS

fe