

WTC Visual Survey Form

1000793

Premise Address: 90 WASHINGTON STREET		
Block: 17	☐ Residential ☐ Commercial	Name of Building:
Lot: 29	☐ Mix Use ☐ Other	
# of Stories:	AKA's: 52-54 WEST ST. / 23-31 RECTOR STREET	
Building Owner/Management:		Telephone Number: (212) 971-0111
Name: ZAR REALTY-Mark S. Stein		FAX: (212) 465-8854
Address: 394 GIRL Avenue N.Y., N.Y. 10018		# 173
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North ☐ N/A South ☐ N/A East ☐ N/A West ☐ N/A	Inspected		Debris		
	☒ Yes	☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
	☒ Yes	☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
	☒ Yes	☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description:					
Roof					
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description: <u>BELOW COOLING TOWERS</u>					
Setbacks ☐ N/A					
Floor: 13	Debris: ☐ No Visible/Fine Layer		☒ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Comments					
<u>GRAVEL SETBACK ON 13th FLOOR</u>					
<u>FORM COMPLETED BY P.T BASED ON TELEPHONE</u>					
<u>REPORT FROM RAMMOHAN AND DATABASE</u>					

Date: 10/18/2002

Inspection Team: Name: RAMMOHAN

Agency: DEP

Name: _____

Agency: _____

ENTERED

WTC Visual Survey Form

1000793

Premise Address: 90 WASHINGTON STREET		
Block: 17	Residential ☐ Commercial ☐	Name of Building:
Lot: 29	Mix Use ☐ Other ☐	
# of Stories:	AKA's: 52-54 WEST ST. / 23-31 RECTOR STREET	
Building Owner/Management:		Telephone Number: (212) 971-0111
Name: ZAR REALTY-Mark S Stein		FAX: (212) 465-9554
Address: 384 Fifth Avenue NY, N.Y. 10018		# 177
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:			
North ☐ N/A	Inspected ☒ Yes ☐ No	Debris ☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
South ☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
East ☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
West ☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
Facade Description: _____			
Roof			
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"			
Description: BELOW COOLING TOWERS			
Setbacks N/A ☐			
Floor: 13	Debris: ☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Comments			
GRAVEL SETBACK ON 13th FLOOR			
FORM COMPLETED BY P.T BASED ON TELEPHONE REPORT FROM RAMMOHAN AND DATABASE			

Date: **10 / 18 / 2002**

Inspection Team: Name: **RAMMOHAN**

Agency: **DEP**

Name: _____

Agency: _____

ENTERED