



The City of New York
Department of
Environmental
Protection

59-17 Junction Boulevard
 Flushing, New York
 11373-5108

Christopher O. Ward
Commissioner

September 3, 2002

TO: 90 Washington LLC c/o ZAR Realty
 384 5th Avenue
 New York, NY 10018-8103

RE: 90 WASHINGTON STREET
 52-54 West Street/23-31 Rector St
FINAL NOTICE

Dear 90 Washington LLC c/o ZAR Realty:

I am writing with regard to 90 WASHINGTON STREET which was inspected by DEP on 02/27/02. During this inspection, debris from the collapse of the World Trade Center towers was observed on the exterior surfaces of the building.

You have been previously contacted with regard to participating in DEP's Lower Manhattan Building Cleaning Program. Under this program, contractors retained by DEP will clean all exterior building surfaces affected by World Trade Center debris at no cost to the building owner.

The Building Cleaning Program is now drawing to a close, and we have yet to receive a response from you regarding your participation. If you do not participate in the Program, the building will be scheduled for another DEP inspection in the near future. If that inspection shows that there is still visible debris from the World Trade Center on the exterior of the building, samples will be collected. If laboratory analysis of these samples shows that the debris is asbestos-containing material, you will then be issued a Commissioner's Order directing you to retain a contractor to clean the exterior of the building. Such cleaning would be at your expense, and failure to comply with the Commissioner's Order could result in the issuance of notices of violation carrying penalties of up to \$10,000 per day.

You are strongly urged to take advantage of the Building Cleaning Program. A blank License Agreement has been attached for your convenience. Please fill in the appropriate information and sign and return the form as soon as possible.

If you have any questions, please call 718-595-3682 during office hours, or the 24-hour Help Center at 718-DEP-HELP. Your cooperation is greatly appreciated.

Sincerely,

R. Radhakrishnan, P.E.

Director

Asbestos Control Program



www.nyc.gov/dep

(718) DEP-HELP

WTC Visual Survey Form

Premise Address: 90 Washington St		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories: 2	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	☐ Yes ☐ No	Debris	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"
Facade Description: No Access					
Roof					
Debris: ☐ No Visible /Fine Layer ☐ 1/2 to 1" ☐ > 1"					
Description:					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Comments ?					

Date: 8/30/2002 Inspection Team: Name: CARC Agency: _____
 Name: _____ Agency: _____

ENTERED

WTC Visual Survey Form

Premise Address: <u>90 Washington St - (closed)</u>		
Block: Lot:	Residential ☐ Commercial ☐ Mix Use ☐ Other ☐	Name of Building: <u>Bank of NY</u>
# of Stories:	AKA's:	
Building Owner/Management: Name:		Telephone Number: ()
Address:		FAX: ()
On Site Contact: Name:		Telephone Number: ()
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:			
North	☐ N/A	Inspected	Debris
South	☒ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
West	☒ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
Facade Description: <u>error</u>			
Roof			
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"			
Description: _____			
Setbacks N/A ☐			
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Comments			

Date: 1/26 2002

Inspection Team: Name: Carroll
Name: _____

Agency: DEP
Agency: _____