

WTC Visual Survey Form

Premise Address: 105 Washington St		
Block:	Residential ☐ Commercial ☐	Name of Building: Buddhist Temple
Lot:	Mix Use ☐ Other ☐	
# of Stories: 7	AKA's:	
Building Owner/Management:		Telephone Number: (718) 417-5177
Name: Sheng Yan Lu		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☒ No		
Exterior Survey Performed ☐ Yes ☒ No		
General Clean Up ☒ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☒ No Locations: _____		
Air Monitoring ☐ Yes ☒ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☒ N/A	Inspected	Debris	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
South	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"	
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"	
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"	
Facade Description:					

Roof					
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description: Pockets of debris - at various locations - minimal					

Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 1/26/2002

Inspection Team: Name: CARL

Agency: DCR

**ASBESTOS CONTROL PROGRAM
EMERGENCY RESPONSE
DIAGRAM**

NAME <u>AL PLUMPTRE</u>	BADGE # <u>AOL</u>	DATE <u>4/27/02</u>
LOCATION <u>105 1/2 WASHINGTON ST</u>		
9 - 11 (1) PHOTOGRAPHS ROOF ☒ No Visible Debris ☐ Entire Roof Covered with Debris ☐ Partial Roof Covered ☐ Local/Isolated Areas ☐ Gutters ☐ 25% of the roof ☐ 50% of the roof ☐ 75% of the roof FACADE ☒ Clean ☐ Entire Facade req. Clean-up ☐ _____ Req. Clean-up		