

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Inspection Detail

Report Date 03/19/2002 11:37 AM

Submitted By

Page 1

Service # 416966
Problem BWTC ASBESTOS: WTC (USE COMMENTS)
Address 380 RECTOR PL 1
10280
Cross Streets S END AVE

70

Compass Direction

Building ID 10005

Block 00016

Lot 7505

CMBD 101

Location

Area

Sub-Area 101

District

Parcel

of Calls 1
Taken By 2999
Responsibility BHZ
Scheduled Date 03/16/2002 09:00
Inspector 4230
Due Date
Resolution Code B5
Asset
Avg Insp Duration
Avg Insp Days 0
Avg Insp Hrs 0
Avg Insp Mins 0

Duration of Call 00:00
GERENA, TASHA
BANHAZMAT (AIR, NOISE, HAZ. MAT)
LUTCHMEDIAL, CARLSTIE
ASBESTOS, CLEAN-UP ORDERED

Call Date 03/05/2002 10:57
Priority
Start Date 03/16/2002 09:00
Inspection Date 03/16/2002 09:00
☐ No Work Orders Required
Resolution Date 03/16/2002 09:30

☐ Customer Contact Req
Budget #

COMPLETED

Problem Comments **PII** said that they never called the DEP. she said that she had faxed the sample results to a couple of people and wasn't sure how DEP was notified. she was concerned about the air on the street and the parks. also whether it was safe for her child who lives in the apartment with her. inspection revealed that there was no visible dust or debris inside the apartment or window ledges.

Initial Caller

Last Name

First Name, MI

Address

Title

PII

City, State/Province, ZIP/PC

☐ Foreign

Day Phone

Evening Phone

Call Date 03/05/2002 10:57

Reference #

Caller Comments REQUESTING DUST WITE SAMPLING

Work Orders Work Order # Priority	Activity Problem	Asset Project	Act.Type Fr Type	Act Group Unit ID	Initiated	Scheduled To Type	Completed Unit ID	Source	Maint Type #
---	---------------------	------------------	---------------------	----------------------	-----------	----------------------	----------------------	--------	-----------------

There are no work orders for this service number

Assets

Asset	From Type	Unit ID	To Type	Unit ID	#	Qualifier
-------	-----------	---------	---------	---------	---	-----------

There are no assets

Linked Requests

Service #	Problem	Problem Date	Address
-----------	---------	--------------	---------

No Linked Requests for this Service Request Inspection

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Dispatch Detail

Report Date 03/05/2002 12:44 PM

Submitted By

Page 1

Service # 416966

Problem BWTC ASBESTOS: WTC (USE COMMENTS)

Address 380 RECTOR PL 1

10280

Cross Streets S END AVE

Compass Direction

Building ID 10005

Block 00016

Lot 7505

CMBD 101

Location

Area

Sub-Area 101

District

Parcel

of Calls 1

Duration of Call 00:00

Call Date 03/05/2002 10:57

Taken By 2999

GERENA, TASHA

Responsibility BHZ

BANHAZMAT (AIR, NOISE, HAZ. MAT)

Priority

Scheduled Date

Inspector

Due Date

Asset

Avg Insp Duration

☐ Customer Contact Req

Budget #

Avg Insp Days 0

Avg Insp Hrs 0

Avg Insp Mins 0

COMPLETED

Problem Comments

Initial Caller

Last Name

First Name, MI

Address

Title

PII

City, State/Province, ZIP/PO

☐ Foreign

Day Phone

Evening Phone

Call Date 03/05/2002 10:57

Reference #

Caller Comments

REQUESTING DUST WITE SAMPLING

Inspected

Resolution

By

Date

Time

Code

Date

Time

Left message for Mr. Timothy J. Donohoe
He fax the paper to her.

Saturday
9:00am

Thurs.
10 AM - 12 noon

Fri.

~~Morning 10am - 12 noon~~

2/16/2002 11:44

212-290-0050

EMSL MANHATTAN

PAGE 8

New York Lab

West 90th Street, New York, NY 10018
Tel: 212-290-0051 Fax: 212-290-0054 Email:

Donohoe Environmental, Inc.
99 Bowery #604
New York, NY 10002

(212) 673-7215
300 Rector Pl Apt 18G

Phone: 212-260-9818

Customer ID: DMUE21
Customer PO:

Received: 02/14/02 10:10 AM
EMSL Order: 030201084
EMSL Project ID:

Analysis Date: 2/16/02

Asbestos Analysis via Transmission Electron Microscopy ASTM Method D6400-99

AREA SAMPLED (sq ft)	ASBESTOS TYPE	ASBESTOS STRUCTURES	Sensitivity (ppm/m ³)	CONCENTRATION (ppm/m ³)	COMMENTS
1001	39 Chrysotile	108	6117.333	860437.333	
1002	39 Chrysotile	112	6764.444	787817.778	
1003	39 Chrysotile	86	4058.987	349045.333	

Emilio B. B.
Laboratory Manager
or other approved signatory

This report applies only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc.

**DONOHUE ENVIRONMENTAL, INC.**

39 Bowery #684 New York, New York 10002

Phone: 212 260-9818

Fax: 212 673-7215

February 7, 2002

PII

380 Rector Place, Apartment
New York, New York 10280

PII

Re: Wipe sampling at 380 Rector Place, Apartment PII in New York City on 2/14/02.

Dear PII

Enclosed are the results of the fiber analysis for the TIM wipe samples collected on February 14, 2002. Results are presented on the enclosed tables.

Wipe samples were collected from the small bedroom window, living room window, and master bedroom window. Samples were analyzed with ASTM Method D-6480-99. Some asbestos fibers were found on the wipe samples. Asbestos structures were detected on all of the samples. We recommend that the apartment be wet wiped, HEPA vacuumed and the exposed furniture covering be washed. The dust on the outside of the windows should be considered asbestos containing dust and cleaned properly.

Bulk samples were collected from the air filters in the bedrooms and analyzed with PLM Microscopy, neither sample contained asbestos.

All analyses were performed by EMSL Analytical, (ELAP 11506, NVLAP 101048-9).
Feel free to call if you have any problems or need more information.

Sincerely,

Timothy J. Donohue
Donohue Environmental, Inc.

Post-It® Fax Note	7871	Date	3-4	# of pages	2
To	Krish Radhakrishnan	From	Same		
Co./Dept.		Co.			
Phone #	FYI	Phone #			
Fax #		Fax #			