

WTC Visual Survey Form

Premise Address: 2 Rector St

Block: 51 **Residential** ☐ **Commercial** ☒ **Name of Building:** _____
Lot: 1 **Mix Use** ☐ **Other** ☐

of Stories: 26 **AKA's:** 2-12 Rector St / 56-66 Trinity Place / 91-101 Greenwood St

Building Owner/Management: Serry Inc. - Ch. Eng. **Telephone Number:** (212) 619 5920
Name: _____ **FAX:** () _____

Address: 2 Rector St **Telephone Number:** (212) 619 5920

On Site Contact: Serry **Telephone Number:** () _____
Name: _____

Building Owner Management Activities
Interior Survey Performed ☒ Yes ☐ No
Exterior Survey Performed ☒ Yes ☐ No
General Clean Up ☒ Yes ☐ No **Locations:** No ACM from Samples
ACM Clean Up ☐ Yes ☒ No **Locations:** _____
Air Monitoring ☒ Yes ☐ No **Locations:** _____

Copies of All Reports and Data Requested ☒ Yes

Visual Inspection Results:

Facade:

	Inspected	Debris
North ☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
South ☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
East ☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
West ☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"

Facade Description: _____

Roof

Debris: ☐ No Visible /Fine Layer ☐ 1/2 to 1" ☒ > 1"

Description: Very dirty

Setbacks ☐ N/A

Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"

Comments Air Results summary sheet given show samples were negative. None of Roof.

Date: 1/25/2002 **Inspection Team: Name:** Chris Hutchinson **Agency:** DER
Name: _____ **Agency:** _____

WTC Visual Survey Form

Premise Address: <u>2 RECTOR ST</u>		
Block: Lot: <u>26</u>	Residential ☐ Commercial ☒ Mix Use ☐ Other ☐	Name of Building:
# of Stories: <u>26</u>	AKA's:	
Building Owner/Management: Name: <u>Serry Mitchell - Ch. Eng.</u>		Telephone Number: <u>(212) 619 5920</u>
Address: <u>184g W 4th St</u>		FAX: <u>(212) 619 5920</u>
On Site Contact: Name: <u>Serry</u>		Telephone Number: <u>()</u>
Building Owner Management Activities Interior Survey Performed ☒ Yes ☐ No Exterior Survey Performed ☒ Yes ☐ No General Clean Up ☒ Yes ☐ No Locations: <u>No ACM from Samples</u> ACM Clean Up ☐ Yes ☒ No Locations: _____ Air Monitoring ☒ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:			
North ☒ N/A	Inspected ☐ Yes ☐ No	Debris ☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
South ☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
East ☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
West ☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
Facade Description: _____			
Roof			
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☒ > 1"			
Description: <u>Very dirty</u>			
Setbacks N/A ☐			
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Comments			
<u>Air Results Summary Sheet given show</u>			
<u>samples were negative. None of Roof.</u>			

Date: 1/25/2002Inspection Team: Name: CARL HUTCHINGSAgency: DEP

Name: _____

Agency: _____

WTC Visual Survey Form

Premise Address: <u>2 RECTOR ST</u>		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories: <u>26</u>	AKA's:	
Building Owner/Management:		Telephone Number: <u>(212) 619 5920</u>
Name: <u>Serry Vincent - Ch. Eng.</u>		FAX: <u>()</u>
Address: <u>184 W 4th St Victor Purpura</u>		<u>(212) 619 5920</u>
On Site Contact:		Telephone Number: <u>()</u>
Name: <u>Serry</u>		
Building Owner Management Activities		
Interior Survey Performed ☒ Yes ☐ No		
Exterior Survey Performed ☒ Yes ☐ No		
General Clean Up ☒ Yes ☐ No Locations: <u>No Acum from Samples</u>		
ACM Clean Up ☐ Yes ☒ No Locations: _____		
Air Monitoring ☒ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:					
North	☒ N/A	Inspected	☐ Yes ☐ No	Debris	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☐ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☐ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☐ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
Facade Description: _____					
Roof					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☒ > 1"					
Description: <u>Very dirty</u>					
Setbacks ☐ N/A					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					
<u>AIR Results summary sheet given show</u>					
<u>samples were negative. None of Roof.</u>					

Date: 1/25/2002Inspection Team: Name: Mr. HutchinsonAgency: DEP