

WTC Visual Survey Form

Premise Address: 50 TRINITY Place			
Block: 19	Residential ☐	Commercial ☒	Name of Building: Cape World
Lot: 24	Mix Use ☐	Other ☐	
# of Stories: 3	AKA's: S Recto St		
Building Owner/Management:		Telephone Number: ()	
Name: XIONG		FAX: ()	
Address:			
On Site Contact:			
Name: XIONG		Telephone Number: ()	
Building Owner Management Activities			
Interior Survey Performed ☐ Yes ☐ No			
Exterior Survey Performed ☐ Yes ☐ No			
General Clean Up ☐ Yes ☐ No		Locations: _____	
ACM Clean Up ☐ Yes ☐ No		Locations: _____	
Air Monitoring ☐ Yes ☐ No		Locations: _____	
Copies of All Reports and Data Requested ☐ Yes			

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☒ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description:

masonry windows etc...

Roof

Debris: ☒ No Visible /Fine Layer ^{light dust} ☐ ½ to 1" of dust ☐ > 1" of dust.

Description:

Inspected from Roof of 46 TRINITY Pl

Setbacks

N/A ☒

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 1/25/2002

Inspection Team: Name:

Carol Hutchinson

Agency: DGP

Name:

Agency:

Date: 1/30/ 2 Time: 08:28:23 AM