WTC Visual Survey Form

Premise Address: 333 Rector Pl

Block: / **Lot:**	Residential ☒ Commercial ☐ Mix Use ☐ Other ☐	**Name of Building:**
# of Stories: 13	**AKA's:**	

Building Owner/Management:
Name: ~~Milford Management~~ Rockrose Development Corp
Telephone Number: (212) 375-1155
FAX: ( )
Address:

On Site Contact:
Name:
Telephone Number: ( )

Building Owner Management Activities

- Interior Survey Performed ☑ Yes ☐ No
- Exterior Survey Performed ☑ Yes ☐ No
- General Clean Up ☑ Yes ☐ No Locations:
- ACM Clean Up ☐ Yes ☐ No Locations:
- Air Monitoring ☑ Yes ☐ No Locations:

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☑ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☑ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☑ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☑ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: Brown windows etc No visible debris

Roof

Debris: ☑ No Visible /Fine Layer ☐ ½ to 1" 1 test ☐ > 1" 1 test.
Description:

Setbacks N/A ☐

Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments
No visible debris on the roof and facade

Date: 1/28/2002
Inspection Team: Name: AL Agency: DEP
Name: Rob Agency: DEP

A2R24

WTC Visual Survey Form

Premise Address: 333 Rector Pl

Block: **Lot:**	Residential ☒ Commercial ☐ Mix Use ☐ Other ☐ _____	**Name of Building:**
# of Stories: 13	**AKA's:**	

Building Owner/Management:
Name: ~~Milford Management~~ Rockrose Development Corp
Telephone Number: (212) 375-1155
FAX: ( )
Address:

On Site Contact:
Name:
Telephone Number: ( )

Building Owner Management Activities

Interior Survey Performed	☑ Yes	☐ No	
Exterior Survey Performed	☑ Yes	☐ No	
General Clean Up	☑ Yes	☐ No	Locations:
ACM Clean Up	☐ Yes	☐ No	Locations:
Air Monitoring	☑ Yes	☐ No	Locations:

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☑ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☑ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☑ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☑ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: Brown window sills etc No visible debris

Roof

Debris: ☑ No Visible /Fine Layer (light dust) ☐ ½ to 1" (1 test) ☐ > 1" (1 test)
Description:

Setbacks N/A ☐

Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: ____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments
No visible debris on the roof and facade

Date: 1/28/2002
Inspection Team: Name: AL Agency: DEP
Name: KOL Agency: DEP

Page: 1 Document Name: Extra

```
  ADDRESS EXISTS WITH A.K.A.S WHICH HAVE THE SAME BIN
  01/30/02        PUBLIC ACCESS PROPERTY PROFILE OVERVIEW              BISPIQ70
  333..... RECTOR PLACE.................. 1 MANHATTAN     10280 BIN# 1000055

  RECTOR PLACE          303 - 333          HEALTH AREA : 89     TAX BLK: 16...
  SOUTH END AVENUE      213 - 215          CENSUS TRACT:  31701 TAX LOT: 80...
                                           COMMUNITY BD: 101    CONDO  :
                                           MULTI STRUCT: 01     VACANT :
  ================================================================================
  DOB SPECIAL PLACE NAME :                                 1   PROPERTY RECORD(S)
  DOB BUILDING REMARKS   :
  FINANCE OCCUPANCY CODE : Y7-GOVERNMENT INSTAL  LANDMARK STATUS:

   COUNTS FOR THIS BIN                                    RECORD VERIFIED :
   ACTIONS          : 19    , 9     JOBS/FILINGS (PF4)     SPECIAL STATUS :
   VIOLATIONS DOB   : 6     , 0     OPEN                        LOCAL LAW :
              ECB   : 3     , 0     OPEN    (PF12)                   SRO :
   COMPLAINTS       : 2     , 0     OPEN    (PF11)

  PF 3 = ELEVATORS    ENTER KEY= ACTIONS  PF 5/6/7 = NEW ADDR/BIN/BLK-LOT
  PF 8 = BOILERS      (TYPE : ....  )     PF 9/10  = BROWSE BIN/BLK-LOT
  PF 13 = PRA/ARA                         PF 15    = BROWSE 1   PROPERTY RECORDS
  PF 14 = LPC/HPD/LOFT USE ONLY           PF 16    = ADDTN'L PROPERTY INFO
```

Date: 1/30/ 2 Time: 01:38:31 PM