

WTC Visual Survey Form

Premise Address: <u>200 Repton Pl.</u>		
Block:	Residential ☒ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management Name:		Telephone Number: ()
		FAX: ()
Address:		
On Site Contact:		
Name: <u>ELIOT Ruiz - Designer</u>		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed	☐ Yes ☐ No	Re-inspect
Exterior Survey Performed	☐ Yes ☐ No	
General Clean Up	☐ Yes ☐ No	
ACM Clean Up	☐ Yes ☐ No	
Air Monitoring	☐ Yes ☐ No	
		Locations: _____
		Locations: _____
		Locations: _____
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	☐ Yes ☐ No	Debris	☐ No Visible/Fine Layer
South	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
Facade Description:					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: <u>Gravel Roof</u>					
Setbacks ☒ N/A					
Floor: <u>9</u>	Debris: ☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 5/18/2002Inspection Team: Name: CARLAgency: _____
Agency: _____

ENTERED

Summary of Inspections @ 200 Rector Place

2/15/2002 – [PII] – Inspection revealed that there was no visible WTC.

2/21/2002 – [PII] – Visited the Building twice [PII] was not at home even though she had an appointment. The second visit the doorman said she was home but was not answering. In addition, the phone number came on as a fax machine.

2/25/2002 – [PII] appeared with a dust mask on her face. She informed me that there are four carcinogens in the air. She went on to say that one of them is asbestos. However, based on testing of her apartment for asbestos, none was found. Inspection of her apartment revealed that there was no visible WTC debris. The apartment was extremely untidy with clothes, paper, and boxes scattered everywhere. Some pieces of floor boards was also missing. She kept talking about policies of various agencies. She also kept addressing fiberglass as a carcinogen which she said needs to be cleaned up. I informed her that based on my observations and her own sample results there was nothing that DEP could do.

3/06/2002 – [PII] – Inspection revealed that there was no visible WTC debris in the apartment [PII] wanted to have the air in the apartment tested. She was faxed a copy of various air monitoring contractors.

3/12/2002 [PII] Inspected the apartment along with [PII] she said they were concerned about dust accumulation on the ceiling. Inspection revealed that there was no WTC debris on the ceiling. She was also concerned about the air being tested. She was informed that it had to be done privately.

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Dispatch Detail

Report Date 02/25/2002 12:53 PM

Submitted By

Page 1

Service # 413027

Problem BWTC ASBESTOS: WTC (USE COMMENTS)

Address 200 RECTOR PL 1

10280

Cross Streets BEND
S END AVE

Compass Direction

Building ID 10654

Block 00016

Lot 7508

CMBD 101

Location

Area

Sub-Area 101

District

Parcel

of Calls 1

Duration of Call 00:00

Call Date 02/21/2002 18:02

Taken By 6407

STRAITZ, ROSEANN

Responsibility BHZ

BANHAZMAT (AIR,NOISE,HAZ.MAT)

Priority

Scheduled Date

Inspector

Due Date

Asset

Avg Insp Duration

☐ Customer Contact Req

Budget #

Avg Insp Days 0

Avg Insp Hrs 0

Avg Insp Mins 0

COMPLETED

Problem Comments

Initial Caller

Last Name

PII

Title MS

First Name, MI

Address

PII

City, State/Province, ZIP/PC

☐ Foreign

Day Phone

PII

Evening Phone

Call Date 02/21/2002 18:02

Reference #

Caller Comments

dust in bldg & in complts apt. complt states that it is coming from ground zero & there is fiberglass containment in the bldg. phone & fax # the same. wants a crew there tomorrow.

Inspected

Resolution

By	Car	Date	2/21/02	Time	4:15	Code	B	Date	2/21/02	Time	4:15
----	-----	------	---------	------	------	------	---	------	---------	------	------

No Accen

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Dispatch Detail

Report Date 02/25/2002 01:27 PM

Submitted By

Page 1

Service # 413154

Problem BWTC ASBESTOS: WTC (USE COMMENTS)

Address 200 RECTOR PL 1

10280

Cross Streets BEND
S END AVE

Compass Direction

Building ID 10654

Block 00016

Lot 7508

CMBD 101

Location

Area

Sub-Area 101

District

Parcel

of Calls 1

Duration of Call 00:00

Call Date 02/22/2002 09:54

Taken By 6350

STALZER, HENRIETTA T.

Responsibility BHZ

BANHAZMAT (AIR, NOISE, HAZ. MAT)

Priority

Scheduled Date

Inspector

Due Date

Asset

Avg Insp Duration

Avg Insp Days 0

Avg Insp Hrs 0

Avg Insp Mins 0

☐ Customer Contact Req

Budget #

COMPLETED**Closed**

Problem Comments

Initial Caller

Last Name

PII

Title MS

First Name, MI

Address

200 RECTOR PL

PII

City, State/Province, ZIP/PC NEW YORK

NEW YORK

10280

☐ Foreign

Day Phone

PII

Evening Phone

Call Date 02/22/2002 09:54

Reference #

Caller Comments

dep meeting with mgt in building regarding wtc ait problems caller would like to be in on it, please cont compl

Inspected

Resolution

By	Date	Time	Code	Date	Time

~~Busy~~
The Line is Busy
for the last 3 days
Every time I call it is busy
Called 3/13/02 it is busy
Not the right number

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Dispatch Detail

Report Date 02/28/2002 03:14 PM

Submitted By

Page 1

Service # 415139
Problem BWTC ASBESTOS: WTC (USE COMMENTS)
Address 200 RECTOR PL 1
10280
Cross Streets BEND
S END AVE
Compass Direction
Building ID 10654 Block 00016 Lot 7508 CMBD 101

Location
Area
Sub-Area 101 District
Parcel

of Calls 1 Duration of Call 00:00 Call Date 02/28/2002 08:10
Taken By 6350 STALZER, HENRIETTA T.
Responsibility BHZ BANHAZMAT (AIR, NOISE, HAZ. MAT) Priority
Scheduled Date
Inspector
Due Date
Asset

Avg Insp Duration

Avg Insp Days 0
Avg Insp Hrs 0
Avg Insp Mins 0

COMPLETED

☐ Customer Contact Req
Budget #

Problem Comments

Initial Caller

Last Name PII Title MR
First Name, MI
Address 200 RECTOR PL PII
City, State/Province, ZIP/PC NEW YORK NEW YORK 10280
☐ Foreign
Day Phone PII Evening Phone Call Date 02/28/2002 08:10
Reference #

Caller Comments lives in liberty court, had apt cleaned since wtc, still concerned about asbestos, cont compl, pls leave message or call early am btw 7 & 9

Inspected			Resolution		
By	Date	Time	Code	Date	Time

Left message.

Gave to Carl

PII

is Disconnected

Called at 12:45 pm 3/4/02

Left message at 3:15 3/5/02

Tues, ~~Wed~~, Thurs 3/12/02~~Anytime~~ 2:00 - 4:00

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Inspection Detail

Report Date 03/13/2002 11:50 AM

Submitted By

Page 1

Service # 417313

Problem BWTC ASBESTOS: WTC (USE COMMENTS)

Address 200 RECTOR PL 1

10280

Cross Streets BEND

S END AVE

Compass Direction

Building ID 10654

Block 00016

Lot 7508

CMBD 101

Location

Area

Sub-Area 101

District

Parcel

of Calls 1

Duration of Call 00:00

Call Date 03/06/2002 09:51

Taken By 6350

STALZER, HENRIETTA T.

Responsibility BHZ

BANHAZMAT (AIR,NOISE,HAZ.MAT)

Scheduled Date 03/11/2002 16:00

Priority

Inspector 4230

LUTCHMEDIAL, CARLSTIE

Start Date

03/11/2002 16:00

Due Date

Inspection Date

03/11/2002 16:00

Resolution Code BZ1

ASBESTOS,OTHER

☐ No Work Orders Required

Resolution Date 03/11/2002 16:30

Asset

Avg Insp Duration

☐ Customer Contact Req

Budget #

Avg Insp Days	0
Avg Insp Hrs	0
Avg Insp Mins	0

COMPLETED

Problem Comments Ms Cummings wanted to have the air in her apartment tested. she had her apartment professionally cleaned a couple of times since WTC incident. the apartment was very clean now. she had no concerns for any visible dust. it was just the air which she believes was causing her husband's emphysema. a list of air monitoring companies was faxed to her.

Initial Caller

Last Name

PII

Title MS

First Name, MI

Address 200 RECTOR PL

PII

City, State/Province, ZIP/PC MANHATTAN

☐ Foreign

Day Phone

PII

Evening Phone

Call Date 03/06/2002 09:51

Reference #

Caller Comments lives near wtc, request inspection of home, husband ill with emphysema and other thing, concerned about the air quality, cont compl

Work Orders

Work Order #

Activity

Asset

Act Type

Act Group

Initiated

Scheduled

Completed

Source

Maint Type

Priority

Problem

Project

Fr Type

Unit ID

To Type

Unit ID

#

There are no work orders for this service number

Assets

Asset

From Type

Unit ID

To Type

Unit ID

#

Qualifier

There are no assets

Linked Requests

Service #

Problem

Problem Date

Address

Location

No Linked Requests for this Service Request Inspection