

ASBESTOS INSPECTION REPORT

REMISE NO. 92		STREET READE STREET			INSPECTION DATE 7-31-02	
LOOR Roof	ZIP	BORO CODE 1	BLOCK 146	LOT 1	SQUAD # 1	BADGE # AD10
INSPECTOR ALPHONSO PLUMPTRE		BLDG TYPE	BASIS OF INSPECT. TRU 1173mp		PHOTOS TAKEN YES/NO	
CONTRACTORS NAME FIBER CONTROL				SAMPLE NO.		
ADDRESS 3010 BURNS AVE. CITY WANTAGH				SAMPLE NO.		
STATE N.Y. ZIP 11793 PHONE (616) 781-3000				SAMPLE NO.		
LABORATORY NAME WARREN & PAUZER ENGINEERS, PC				OWNERS NAME Mr. Herbert Moskowitz		
ADDRESS 228 E. 45TH ST CITY N.Y.				P11		
STATE N.Y. ZIP 10017 PHONE (212) 922-0077				STATE N.Y. CP 10013 PHONE		
CONTACT PERSON:				TIME OF INSPECTION FROM: 11:30 am TO: 12:15 am		
INSPECTION DISCLOSED:						

The roof was inspected after the cleanup and there was no visible debris observed after the cleanup.

NOV #	#INFRACTIONS					RESULT CODE 5
NOV #						SUPERVISORS INITIALS <i>OK</i>

BORO 1 - MANHATTAN 2 - BRONX 3 - BROOKLYN 4 - QUEENS 5 - RICHMOND

BLDG TYPE A > 6 Stories B < 6 Stories C Single Family
D School E Hospital F Public Owned Property

RESULT CODES 1 - Violation Issued 2 - No Violations Issued 3 - No Access
4 - Project not Started (No NOV) 5 - Project Completed (No NOV)

ACP 309