

ASBESTOS INSPECTION REPORT

REMISE NO.		STREET				INSPECTION DATE	
94		Reade St				7-31-02	
LOOR	ZIP	BORO CODE	BLOCK	LOT	SQUAD #	BADGE #	
Roof	10013	1	146	2	1	AD10	
INSPECTOR		BLDG TYPE	BASIS OF INSPECT			PHOTOS TAKEN YES / NO	
ALPHONSO PLUMPTRE			TRU 1174MN02				
CONTRACTORS NAME				SAMPLE NO.			
FIBER CONTROL							
ADDRESS				SAMPLE NO.			
3010 BURNS AVE CITY WANTAGH							
STATE	ZIP	PHONE	SAMPLE NO.				
N.Y.	11793	(516) 781-3000					
LABORATORY NAME				OWNERS NAME			
WARREN & PANZER ENGINEERS, PC				Mr. Herbert Moskowitz			
ADDRESS		CITY	PII		CITY		
228 E. 45TH ST		N.Y.			N.Y.		
STATE	ZIP	PHONE	STATE	ZIP	PHONE		
N.Y.	10017	(212) 922-0077	N.Y.	10013			
CONTACT PERSON:				TIME OF INSPECTION FROM: 11:15 am TO: 11:40 am			
INSPECTION DISCLOSED:							

There were no visible debris observed after the cleaning on the roof including the gutters.

NOV #	INFRACTIONS					RESULT CODE
						5
NOV #						SUPERVISORS INITIALS
						AL

BORO 1 - MANHATTAN 2 - BRONX 3 - BROOKLYN 4 - QUEENS 5 - RICHMOND

BLDG TYPE A > 6 Stories B < 6 Stories C Single Family
D School E Hospital F Public Owned Property

RESULT CODES 1 - Violation Issued 2 - No Violations Issued 3 - No Access
4 - Project not Started (No NOV) 5 - Project Completed (No NOV)

ACP 309