

WTC Visual Survey Form

Premise Address: <u>110 Reade Street</u>		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☒ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Name:		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☒ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description:					
Roof					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1" no info / no letters listed as no access					
Description:					
Setbacks N/A ☐					
Floor: _____		Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"		Debris: ☐ > 1"
Floor: _____		Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"		Debris: ☐ > 1"
Floor: _____		Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"		Debris: ☐ > 1"
Floor: _____		Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"		Debris: ☐ > 1"
Floor: _____		Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"		Debris: ☐ > 1"
Comments					

Date: 5 / 1 / 2002Inspection Team: Name: RAMAgency: DEP

Name: _____ Agency: _____

ENTERED

WTC Visual Survey Form

Premise Address: <u>110 Reade street</u>		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☒ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description:					

Roof					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: _____					

Setbacks ☐ N/A					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 5 / 1 / 2002Inspection Team: Name: RAMAgency: DEP

Name: _____

Agency: _____

ENTERED

Page: 1 Document Name: Extra

05/02/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPI031
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
110..... READE STREET..... 1 MANHATTAN 10013 BIN# 1001597
DCP GEOGRAPHICAL INFORMATION:
READE STREET 110 - 110 HEALTH AREA : 77 TAX BLK: 146..
CENSUS TRACT: 2011 TAX LOT: 10...
COMMUNITY BD: 101 CONDO :
MULTI STRUCT: 1 CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : SALIM K SAYAGE SALIM K SAYAGE
CORP. NAME : LPC LANDMARK STATUS: LANDMARK
ADDRESS : PII DOB LOCAL LAW STATUS: NO
DOF BUILDING INFORMATION: TRANS LAND VALUE: 204.000
BLDG SIZE: 0025.00 X 0061.00 TAX EXEMPT FLAG : NO
LOT SIZE: 0024.67 X 0061.58 TAX EXEMPT CLASS:
BLDG CLASS : C5 WALK-UP APARTMENT CITY OWNERSHIP : NO
STORIES : 6 UPDATE DATE : 03/25/02
FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:
OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

Date: 5/2/ 2 Time: 03:07:59 PM