

ATC Associates

104 East 25 Street, New York, NY 10010
 Phone: (212) 353-8280 Fax: (212) 353-8306



Attn: Mr. Fabio Pedone
 Warren & Panzer Engineers, P.C.
 228 E. 45th Street
 New York NY 10017
 Fax: (212) 922-0630 Phone: (212) 922-0077
 Project: NYC DEP, W&P# 1079.01.02
 111 Reade Street

Received: 7/13/02 8:30:00 PM
 ATC Group #: 8487
 Analysis Date: 7/14/88

**Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed
 by EPA 40 CFR Part 763 Final Rule (AHERA)**

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structures 0.5µ-5 µ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm ³) (S/cc)	Notes
001A 8487 -1	1350.00	0.0674	0	None Detected	0	0.0042	<14.83	<0.0042
002A 8487 -2	1350.00	0.0674	0	None Detected	0	0.0042	<14.83	<0.0042
003A 8487 -3	1350.00	0.0674	0	None Detected	0	0.0042	<14.83	<0.0042
004A 8487 -4	1350.00	0.0674	0	None Detected	0	0.0042	<14.83	<0.0042
005A 8487 -5	1350.00	0.0674	0	None Detected	0	0.0042	<14.83	<0.0042

ROMAN PEYSAKHOV

Analyzed by:

MICHAEL A. GORYCKI, Ph.D.

Approved by:

Disclaimer: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm³. This report may not be reproduced, except in full, without written approval by ATC Associates Inc. This report may not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. This report relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysis accuracy and precision) is available upon request.

Accredited for NVLAP PLM/TEM #101187-0, NY State ELAP #10879

**2228 East 45th Street
New York, NY 10017
(212) 922-0077
Fax (212) 922-0630**

WARREN & PANZER ENGINEERS, P. C.
AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

1848

Fax (212) 922-0830

24 hr⁺/a 12 hr⁺/a 6 hr⁺/a 3 hr⁺/a Immediate ⁺/a

PAGE 7 OF 7

ॐ

CLIENT: JWC-DSP

PROJECT: FACADE

LOCATION: 111 Leade St

W&P FILE #: 1074.01.02

LABORATORY: ATC

ANALYSIS METHOD:	PCM	TEM	TEM

circle one

TECHNICIAN: V. Wells

CONTACT:

LLV#:

SCA JOB#:

SAMPLE NUMBER	SAMPLE DESCRIPTION & LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE START STOP	ON	TIME OFF.	TOTAL TIME	VOLUME (liters)	CONCENTR. (lb./cc.)
001A	Entrance to dbic	3		10 10	12:15	14:30	135	1350	
002A	10' abt to entrance of dbic	3		10 10	12:14	14:31	135	1350	
003A	Entr. by Siderwall	3		10 10	12:17	14:32	135	1350	
004A	Left side of Siderwall	3		10 10	12:18	14:33	135	1350	
005A	Right side of Siderwall	3		10 10	12:19	14:34	135	1350	
006	Field	1							
007	Field	1							
008	Sealed	1							

COMMENTS:

SAMPLE BY:

SIGNATURE:

RELEASED BY:

SIGNATURE:

RECEIVED BY:

SIGNATURE:

DATE: _____

DATE: _____

DATE: 07/13/02

19:15

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background



ATC Associates Inc.

104 East 25 Street
New York, NY 10010

TEL: (212) 353-8280 FAX: (212) 353-8306

FACSIMILE TELECOPY TRANSMISSION

To: Mr. Fabio Pedone
Warren & Panzer Engineers, P.C.

Fax #: (212) 922-0630

Date: Thursday, July 14, 1988

Time: 10:35:25 AM

Comments:

From: ROMAN PEYSAKHOV

ATC Group #: 8487

Client Project: NYC DEP. W&P# 1079.01.02
111 Reade Street

Number of Pages: 3
(including cover page)