

William Lacina
Facilities Manager

PII

Phone 212-797-9300 Ext. 0
Fax 212-785-3747
Cell 917-882-9651

Cambridge Management

The Cambridge Club
56 Pine Street
New York, NY 10005

The Embassy
154 West 70th Street
New York, NY 10023

WTC Visual Survey Form

Premise Address: <u>56 Ring ST</u>		
Block:	Residential ☒ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories: <u>12</u>	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name: <u>Cambridge Management</u>		FAX: ()
Address:		
On Site Contact:		Telephone Number: (212) <u>797-9300</u>
Name: <u>William Lacina</u>		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	☐ Yes ☐ No	Debris	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
Facade Description:					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description:					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments <u>Fire escape has no Debris from WTC</u>					

Date: 6, 20 /2002 **Inspection Team: Name:** CARL **Agency:** _____

ENTERED

Name: _____ **Agency:** _____