

WTC Visual Survey Form

1001008

Premise Address: 60 PINE STREET & 6 TH TH		
Block: <u>41</u>	Residential ☐ Commercial ☐ Mix Use ☐ Other ☐	Name of Building:
Lot: <u>13</u>		
# of Stories: <u>6</u>	AKA's:	
Building Owner/Management: <u>Down Town Assoc.</u>		Telephone Number: <u>(212) 422-1982</u>
Name: <u>Ronald Cosgro.</u>		FAX: ()
Address: <u>60 PINE ST. NY NY 10005</u>		
On Site Contact: <u>Super.</u>		Telephone Number: ()
Name: <u>Cesar Vega</u>		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☒ No		
Exterior Survey Performed ☐ Yes ☒ No		
General Clean Up ☒ Yes ☐ No Locations: <u>Washed the roof twice</u>		
ACM Clean Up ☐ Yes ☒ No Locations: _____		
Air Monitoring ☐ Yes ☒ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: _____					
Roof <u>5th & 6th Fl roofs</u>					
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description: <u>visible debris found throughout the roof & on ducts in the rear courtyard.</u>					
Setbacks <u>N/A</u> ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 21 / 9 / 2002Inspection Team: Name: Moham
Name: _____Agency: DEP
Agency: _____