

WTC Visual Survey Form

1077435

1077436

Premise Address: <u>74 & 76 READE STREET</u>		
Block: <u>150</u>	Residential ☒ Commercial ☐	Name of Building:
Lot: <u>10</u>	Mix Use ☐ Other ☐	
# of Stories: <u>5</u>	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Name:		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected ☒ Yes ☐ No	Debris ☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: _____					
Roof					
Debris: ☒ No Visible / Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: <u>Access gained through 72 READE ST</u>					
Setbacks N/A ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 4/10/2002Inspection Team: Name: PammohanAgency: DEP.

Name: _____ Agency: _____

ENTERED



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

April
~~February~~ 10, 2002

Building Owner Name: The Building Owner.
Address: 74-76 Reade Street
NYC, NY
Subject: 74-76 Reade Street

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan
R. Radhakrishnan, P.E.
Director
Asbestos Control Program



Page: 1 Document Name: Extra

```

04/15/02          N.Y.C. DEPARTMENT OF BUILDINGS          BISPI031
          MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
74..... READE STREET..... 1 MANHATTAN          10007 BIN# 1077435
DCP GEOGRAPHICAL INFORMATION:
READE STREET          74 - 74          HEALTH AREA : 77          TAX BLK: 150..
READE STREET          76 - 76          CENSUS TRACT: 1010          TAX LOT: 10...
                                          COMMUNITY BD: 101          CONDO :
                                          MULTI STRUCT: 2          CUI NO :

DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : READE ST TENANTS CORP          READE ST TENANTS CORP
CORP. NAME :                                LPC LANDMARK STATUS: NO
ADDRESS : 74          READE ST          DOB LOCAL LAW STATUS: NO
          NEW YORK NY 10007-1845

DOF BUILDING INFORMATION:
BLDG SIZE: ** UNKNOWN **          TRANS LAND VALUE: 0
LOT SIZE: ** UNKNOWN **          TAX EXEMPT FLAG : NO
BLDG CLASS : D4 ELEVATOR APT          TAX EXEMPT CLASS:
STORIES : 0          CITY OWNERSHIP : NO
FOR CITY } MGMT TYPE:          MGMT CODE:          UPDATE DATE : 03/25/02
OWNERSHIP }          MGMT HOLDER CODE:          MGMT CODE NAME:
          MGMT HOLDER CODE NAME:
-----
PF1 =PREV  PF2 =MAIN  PF7 = NEW ADDRESS  PF8 = NEW BLK/LOT  PF9 = NEW BIN

```

Date: 4/15/ 2 Time: 11:39:20 AM

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Inspection Detail

Report Date 03/12/2002 05:54 PM

Submitted By

Page 2

Linked Requests

Service #	Problem Location	Problem Date	Address
-----------	------------------	--------------	---------

No Linked Requests for this Service Request Inspection

NYC DEP

Method

Source

Critical Service

Log Log Type Comments	Description	Log Started	Log Ended	Entered By
-----------------------------	-------------	-------------	-----------	------------

There are no log entries for this service number

End of Report