

Asbestos Inspection Report

Premise No. 215 PEARL STREET					Inspection Date: AS. NOTED	
Floor ROOF & FACADE	Zip 10038	Borough 1	Block 68	Lot 4	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type MIXED USE		Basis of Inspection WTC Survey		Photos Taken ☒ Yes ☐ No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: AS NOTED		

THURSDAY SEPTEMBER 12 2002

THE CLEAN UP OF THE ROOF WORK AREA WAS CONDUCTED TODAY. THE ROOF CLEAN UP OF THE ADJACENT BUILDING, 213 PEARL STREET, WAS PERFORMED SIMULTANEOUSLY. FOR AIR MONITORING PURPOSES THE ROOF AREAS OF THESE TWO BUILDINGS WERE TREATED AS ONE WORK AREA. A REMOTE DECON UNIT WAS ERECTED ON THE ROOF OF 205 PEARL STREET. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY JOHN BOYD (CERTIFICATE # AH 90-05530 EXP 01/03).

FRIDAY SEPTEMBER 13 2002

THE CLEAN UP OF THE WEST (REAR) FACADE WAS CONDUCTED TODAY. THE CLEAN UP OF THE FACADES OF 211 AND 213 PEARL STREET WERE PERFORMED SIMULTANEOUSLY. FOR AIR SAMPLING PURPOSES THE WEST FACADES OF THESE THREE BUILDINGS WERE TREATED AS ONE WORK AREA. AIR SAMPLING WAS PERFORMED BY JOHN BOYD. THE CLEAN UP OF THE SET BACK AREA OF THE PREMISE BEGAN TODAY.

SATURDAY SEPTEMBER 14 2002

THE CLEAN UP OF THE SET BACK AREA IS COMPLETED. AIR SAMPLING WAS PERFORMED BY JOHN BOYD. THE CLEAN UP OF THE EAST FACADE WAS ALSO PERFORMED TODAY. THE CLEAN UP WAS LIMITED TO THE HEPA VACUUMING AND WET WIPING OF WINDOW SURFACES. NO POWER WASHING WAS DONE DUE TO SEVERAL AREAS OF SEVERE CRACKING OF THE BRICK FACADE SURFACE. THE FACADE CLEAN UP OF THE ADJACENT BUILDINGS, 213 AND 211 PEARL STREET OCCURRED SIMULTANEOUSLY. FOR AIR MONITORING PURPOSES THE EAST FACADE OF THESE THREE BUILDINGS WERE TREATED AS ONE WORK AREA. AIR SAMPLING FOR THE FACADE CLEAN UP WAS PERFORMED BY

120

Asbestos Inspection Report

Premise No. <u>215 PEARL STREET</u>	Inspection Date: <u>AS NOTED</u>
Inspector <u>Dennis Antzoulatos</u>	Page <u>2</u> of <u>2</u>

SATURDAY SEPTEMBER 14 2002 (CONT).

OCHOGRHO EDHABOR (CERTIFICATE # AH00-16198 EXP 12/02). A DECON

TRUCK WAS UTILIZED. A BOOM TRUCK WAS USED TO ACCESS THE

FACADE. NO PLASTIC DYKE WAS CONSTRUCTED FOR THIS FACADE

CLEAN UP BECAUSE NO POWER WASHING ACTIVITIES WERE EMPLOYED.

AT THE COMPLETION OF THE CLEAN UP ACTIVITIES I CONDUCTED A

VISUAL INSPECTION OF THE CLEANED SURFACES AND I OBSERVED NO

VISIBLE WTC DEBRIS. THE CLEAN UP PROJECT AT THE PREMISE

IS NOW COMPLETE.

NOTE: THE AREA IN BETWEEN 213 AND 215 PEARL STREET IS LITTERED

WITH CONSTRUCTION DEBRIS AND IS NOT ACCESSIBLE. WTC DEBRIS

MAY BE PRESENT AT THIS LOCATION.

RP