

Asbestos Inspection Report

Premise No. 213 PEARL STREET					Inspection Date: As NOTED	
Floor ROOF & FACADE	Zip 10038	Borough 1	Block 69	Lot 5	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type MIXED USE		Basis of Inspection WTC Survey		Photos Taken ☒ Yes/ No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: As NOTED		
THURSDAY SEPTEMBER 12 2002						
THE CLEAN UP OF THE ROOF WORK AREA WAS CONDUCTED TODAY. THE ROOF CLEAN UP OF THE ADJACENT BUILDING, 215 PEARL STREET, WAS PERFORMED SIMULTANEOUSLY. FOR AIR MONITORING PURPOSES THE ROOF AREAS OF THESE TWO BUILDINGS WERE TREATED AS ONE WORK AREA. A REMOTE DECON UNIT WAS ERECTED ON THE ROOF OF 205 PEARL STREET. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY JOHN BOYD (CERTIFICATE # PII EXP 01/03).						
FRIDAY SEPTEMBER 13 2002						
THE CLEAN UP OF THE WEST (REAR) FACADE WAS CONDUCTED TODAY. THE CLEAN UP OF THE WEST FACADES OF 215 AND 211 PEARL STREET WERE PERFORMED SIMULTANEOUSLY. FOR AIR SAMPLING PURPOSES THE WEST FACADES OF THESE THREE BUILDINGS WERE TREATED AS ONE WORK AREA. AIR SAMPLING WAS PERFORMED BY JOHN BOYD. THE SET BACK WORK AREA CLEAN UPS OF THESE PREMISES BEGAN TODAY.						
SATURDAY SEPTEMBER 14 2002						
THE CLEAN UP OF THE SET BACK AREA IS COMPLETED. AIR SAMPLING WAS PERFORMED BY JOHN BOYD. THE CLEAN UP OF THE EAST FACADE OF THE PREMISE WAS ALSO PERFORMED TODAY. THE EAST FACADE CLEAN UP OF THE ADJACENT BUILDINGS (211 AND 215 PEARL ST) WERE CONDUCTED SIMULTANEOUSLY. FOR AIR SAMPLING PURPOSES THE EAST FACADE OF THESE THREE BUILDINGS WERE TREATED AS ONE WORK AREA. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY CCHOGHO ERHABOR (CERTIFICATE # AH00-16198 EXP 12/02). A DECON TRUCK WAS UTILIZED AND A PLASTIC DYKE WAS CONSTRUCTED (FOR 211 AND 213 PEARL ST ONLY)						

Asbestos Inspection Report

Premise No. 213 PEARL STREET	Inspection Date: AS NOTED
Inspector Dennis Antzoulatos	Page <u>2</u> of <u>2</u>

SATURDAY SEPTEMBER 14 2002 (CONT)

TO CATCH RUN OFF WATER. AT THE COMPLETION OF CLEAN UP ACTIVITIES I CONDUCTED A VISUAL INSPECTION OF THE CLEANED SURFACES AND OBSERVED NO VISIBLE WTC DEBRIS. THE CLEAN UP PROJECT AT THIS PREMISE IS NOW COMPLETE.

NOTE: THE AREA BETWEEN 213 AND 215 PEARL STREET MAY CONTAIN WTC DEBRIS. THE AREA IN BETWEEN THESE TWO BUILDINGS IS LITTERED WITH CONSTRUCTION DEBRIS AND IS NOT ACCESSIBLE.

21