

WTC Visual Survey Form

1001120

Premise Address: <u>218 pearl street</u>			
Block: <u>69</u>	☐ Residential ☐ Commercial	Name of Building:	
Lot: <u>6</u>	☐ Mix Use ☐ Other		
# of Stories:	AKA's:		
Building Owner/Management:		Telephone Number: ()	
Name:		FAX: ()	
Address:			
On Site Contact:		Telephone Number: ()	
Name:			
Building Owner Management Activities			
Interior Survey Performed ☐ Yes ☐ No			
Exterior Survey Performed ☐ Yes ☐ No			
General Clean Up ☐ Yes ☐ No		Locations: _____	
ACM Clean Up ☐ Yes ☐ No		Locations: _____	
Air Monitoring ☐ Yes ☐ No		Locations: _____	
Copies of All Reports and Data Requested ☐ Yes			

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	☐ Yes ☐ No	Debris	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	☐ > 1"
Facade Description: _____					
Roof <u>cutters with debris.</u>					
Debris:	☒ No Visible/Fine Layer ☒ ½ to 1" ☐ > 1"				
Description:	<u>inspected from 205 pearl street.</u>				
Setbacks <u>N/A</u> ☐					
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Comments					
<u>no access to bldg. Information to request data and clean up left at entrance.</u>					

Date: 2/20/2002Inspection Team: Name: MohanAgency: DEP

Name: _____

Agency: _____