NYC 9/11 Public Portal Document

Asbestos Inspection Report

Premise No. 34 PARK ROW AKA ONE BEEKMAN STREET					**Inspection Date:** AS NOTED	
Floor ROOF & FACADE	**Zip** 10038	**Borough** 1	**Block** 90	**Lot** 13	**Squad #** N/A	**Badge #** A020
Inspector Dennis Antzoulatos	**Building Type** COMMERCIAL		**Basis of Inspection** WTC Survey		**Photos Taken** Yes/(No)	
Contractor's Name Benjamin Kurzban & Son Control			**Sample Number** N/A			
Address **City** 1248 Ralph Avenue, Brooklyn			**Sample Number** N/A			
State **Zip** **Phone** NY 11236 (718)531-2900			**Sample Number** N/A			
Laboratory Name Warren & Panzer Engineers Inc.			**Owner's Name**			
Address **City** 228 East 45 Street New York			**Address** **City**			
State **Zip** **Phone** NY 10017 (212) 922-0077			**State** **Zip** **Phone**			
Contact Person			**Time of Inspection from:** AS NOTED			

TUESDAY SEPTEMBER 24 2002 (800AM - 800PM)

THE CLEAN UP OF THE ROOF OF THE PREMISE BEGAN TODAY. A REMOTE DECONTAMINATION UNIT WAS ERECTED ON THE ROOF. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY YURI BEDIN (CERTIFICATE # AH 96-14947 EXP 02/03). FIVE AIR SAMPLES WERE RUN. FOUR AIR SAMPLES WERE RUN ON THE ROOF AND ONE AIR SAMPLE WAS RUN ON THE STAIR WELL LANDING LEADING TO THE ROOF.

WEDNESDAY SEPTEMBER 25 2002 (800AM - 800PM)

THE CLEAN UP OF THE ROOF WAS COMPLETED. THE CLEAN UP OF THE EAST AND SOUTH FACADES WAS CONDUCTED TODAY. AIR SAMPLING FOR THE FACADE CLEAN UPS WAS PERFORMED BY YURI BEDIN OF WARREN & PANZER. UPON COMPLETION OF THE CLEANING ACTIVITIES I CONDUCTED A VISUAL INSPECTION OF THE CLEANED SURFACES AND OBSERVED NO VISIBLE WTC DEBRIS. THE CLEAN UP PROJECT AT THIS PREMISE IS NOW COMPLETE.

RA