

**BENJAMIN KURZBAN
& SON CONTROL, INC.**1248 Ralph Ave.
BROOKLYN, N.Y. 11236**(718) 531-2900**

TO

Dept of Environmental Protection

59-17 Junction Blvd

Corona, NY 11368

INVOICE**1227**

DATE 11/27/02	ORDER NO.
SHIP TO Re: Contract ROF-REM	

SALESPERSON	DATE SHIPPED	SHIPPED VIA	F.O.B. POINT	TERMS	
QUANTITY	DESCRIPTION			UNIT PRICE	TOTAL
>	Registration # CT 82620020015280				
	Pin# 82602WTCROOF2				
	For work completed at 29 Park Row				
	8500 SF @ 2/SF				
	Total Amount due this Invoice				\$17,000.00

R. Rahman
sent to Denise
on 12/10/02

ORIGINAL

Thank You!

E226 WTC


EMERGENCY
ANY
TYPE WRITTEN
FORMS WILL BE
ACCEPTED



NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION

Asbestos Control Program
59-17 Junction Boulevard, 8th Floor, Corona, NY 11368-5107

ASBESTOS PROJECT NOTIFICATION
(ASBESTOS INSPECTION REPORT)



1. NYC DEP
(See fee schedule)

When submitting this form at the NYC Department of Buildings, the original form and three (3) copies with original signatures are required. Submittal at the NYCDEP requires one copy of the form with original signatures. This form must be submitted to the NYC DEP not less than one week in advance of the start of abatement activities.

I. FACILITY

2. Address 29 PARK ROW Borough MAN Zip 10038
AKA _____ 3. Block 90 4. Lot 10
5. Type of Facility COMMERCIAL 6. Name of Building _____

II. BUILDING OWNER

7. Name _____ 8. Contact Person _____
9. Tel. # _____ Fax # _____
10. Address _____ City _____ State _____ Zip _____

III. GENERAL CONTRACTOR

11. Name _____ Tel. # _____

IV. ASBESTOS ABATEMENT CONTRACTOR

12. Name BENJAMIN KURZBAN & SON CONTROL 13. Contact Person LOUIE LANNICO
14. Federal Employer ID. # P11 15. Tel. # (718) 531-2900 Fax # (718) 209-1808
16. Address 1248 RALPH AVENUE City BROOKLYN State NY Zip 11236

V. THIRD PARTY AIR MONITOR

17. Name WARREN & PANZER ENGINEERS INC. 18. Contact Person MICHAEL NOLAN
19. Federal Employer ID. # P11 20. Tel. # (212) 922-0077 Fax # (212) 922-0630
21. Address 228 EAST 45TH STREET City NEW YORK State NY Zip 10017
22. Sample Analysis Laboratory _____ 23. NYS DOH ELAP # _____

VI. PROJECT INFORMATION

24. Starting date for this portion of work 11/18/02 Projected completion date 11/30/02

Asbestos work schedule ☒ Monday ☒ Tuesday ☒ Wednesday ☒ Thursday ☒ Friday ☒ Saturday ☒ Sunday

Shift from: 7⁰⁰ ☒ am ☐ pm to 7⁰⁰ ☐ am ☒ pm

If other,
specify _____

Access to inspect the premises must be provided during the work schedule indicated in this item.

25. Total amount of asbestos-containing material to be abated during this work

8500 Square Feet, and/or 0 Linear Feet



ACP 7
2/2001

NYC DEP
BUREAU OF ENVIRONMENTAL
REMEDATION & ENFORCEMENT

ASBESTOS INSPECTION REPORT (continued)26. Asbestos Hauler IESI, NY NYS DEC Permit # NJ-462 Tel.# (718) 522-2263Disposal Site(s) BlueRidge Landfill PO Box 399 Scotsdale, Pa 17254

27. This asbestos abatement is part of a (Item a through e requires filing of this form with NYC Department of Buildings)

- a) ☐ Demolition b) ☐ Boiler Replacement c) ☐ Sprinkler Replacement d) ☐ Renovation/Alteration
 e) ☐ Fireproofing Replacement f) ☒ Other (Describe) _____

28. TYPE OF ABATEMENT (Check all appropriate boxes)

- ☐ Removal ☐ Enclosure ☐ Encapsulation ☐ Repair ☒ Clean up

29. ABATEMENT PROCEDURE (Check all appropriate boxes)



- ☐ Full Containment ☐ Glovebag ☐ Tent ☐ DEP Variance Application

30. LOCATIONS OF ABATEMENT

Floor(s)	DESCRIBE SECTION OF FLOOR (e.g. entire, east wing, room #, boiler room, lobby, etc.)	AFFECTED SURFACES CONTAINING ACM (e.g. Pipe lagging, ceiling, plenum ducts, storage tanks, decking, etc.)	AMOUNT OF ACM SQUARE FEET LINEAR FEET	DESCRIPTION OF WORK BEING PERFORMED (e.g. running cable, installing fire sprinklers, removing and replacing boilers, etc.)
ROOF		ROOF SURFACE	3600	
"		METAL SURFACES	500	INCLUDES SKY LIGHT
FACADE	WEST FACADE	FACADE SURFACES	2000	
"	EAST FACADE	FACADE SURFACES	2400	

Tel 1900 HND2

31. I hereby declare that the information provided herein is true and complete to the best of my knowledge. I am familiar with Federal, State and NYC laws and regulations applicable to asbestos related work.

WARREN & PANZER ENGINEERS Print Name of Air Monitor  Signature <u>11-15-02</u> Date	B. KURZBAN & SON CONTROL INC. Print Name of Asbestos Contractor  Signature <u>11-15-02</u> Date	Print Name of Applicant (If other than Owner) Signature Date
--	--	--

32. I understand that as the owner of a building where asbestos abatement activity occurs, I am responsible for the performance of the asbestos abatement activities in accordance with the Asbestos Control Program Rules. I have contracted the third party air monitor who is completely independent of all parties involved in the asbestos project. I hereby declare that I have authorized the filing of this notification for the work specified herein.

Print Name of Owner

Signature

NYC DEP

11-15-02

Date

A STAMPED COPY OF THIS FORM INCLUDING AMENDMENTS MUST BE AVAILABLE AT THE WORK SITE.

Any modification of information provided on this form must be reported immediately in writing directly to the NYC DEP ACP.

The requirements of the Asbestos Control Program Rules may not be lawfully avoided or lessened through the performance of work in incremental or piecemeal fashion.

ACP7
2/2001

11/20/2002 05:39 FAX

018

**ATHENICA**

ENVIRONMENTAL SERVICES INC.

Tel. (718) 794-7400

Fax. (718) 794-0085

CLIENT: Warren & Panzer Engineers, P.C.

LABORATORY ID #: T02-11-089

ANALYT. METHODOLOGY: AHERA

FILTER TYPE: M.C.E.

AVERAGE G.O. AREA (mm²): 0.013433

PROJECT: NYC DEP, 29 Park Row

DATE OF REPORT: 11/19/02

DATE OF ANALYSIS: 11/19/02

EFFECTIVE FILTER AREA (mm²): 385**AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY****LABORATORY RESULTS**

CLIENT #	LAB. ID #	LOCATION	VOLUME (ft ³)	G.O.'s ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITIVITY (microg./cm ³)	TOTAL ASBESTOS AIR CONC. (microg./cm ³)	TOTAL ASBESTOS FILTER CONC. (microg./mm ²)	AIR CONC. FOR STRUCT. 0.558<5µm	AIR CONC. FOR STRUCT. >5.0µm	ASBEST. TYPE CHRYS.	AMPHIB. ASBEST. TYPE SPECIFY
011WA	T02-11-089-4155	IWA on roof center of WA	1305	5	0.0672	0.0044	<0.0044	<14.89	NA	NA	NA	NA
021WA	T02-11-089-4156	IWA on roof west section of WA	1305	5	0.0672	0.0044	<0.0044	<14.89	NA	NA	NA	NA
031WA	T02-11-089-4157	IWA on roof east section of WA	1305	5	0.0672	0.0044	<0.0044	<14.89	NA	NA	NA	NA
041WA	T02-11-089-4158	IWA on roof 10ft away of door entrance of roof	1305	5	0.0672	0.0044	<0.0044	<14.89	NA	NA	NA	NA
050WA	T02-11-089-4159	OWA on stair well leading to roof 1 ft of door entrance to roof	1305	5	0.0672	0.0044	<0.0044	<14.89	NA	NA	NA	NA

ANALYST
E. Sioulkri

LABORATORY DIRECTOR
Spiro Dongaris
LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955

- Athenica Environmental Services Inc. (AES), is responsible only for information pertaining to samples taken by its employees.
- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

**228 East 45th Street
New York, NY 10017
(212) 822-0077
Fax (212) 822-0630**

WARREN & PANZER ENGINEERS, P. C.
AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

PAGE 1 OF 1.

Fax (212) 922-0530

CLIENT: NVC. D.E.P.

W8P FILE #: 1079.01.02

CLIENT: NYC D.C.I.
PROJECT: DEP- L-Geo Control
8/27/11

LABORATORY: Warren and Panzer.

LOCATION: 29 Park Row, N.Y. NY. Roof.

ANALYSIS METHOD: PCM TEM TEM
circle one AHERA EPA LEVEL II

TECHNICIAN: Yury Bedin.

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE START STOP	TIME ON OFF	TOTAL TIME	VOLUME (liters)	CONCENTR (flb./cc.)
1 IWA.	on Roof, Center of Work Area.	3		3.0 3.0	9:35 16:50	435	1305	
2 IWA.	on Roof, West Section of Work Area.	3		3.0 3.0	9:37 16:52	435	1305	
3 IWA.	on Roof, East Section of Work Area.	3		3.0 3.0	9:39 16:54	435	1305	
4 IWA.	on Roof, 1072 Area of Drop Entry of Roof. 11-1 of Roof E. of main road.	3		3.0 3.0	9:41 16:56	435	1305	
5 OWA.	on Stairwell leading to Roof.	3		3.0 3.0	9:43 16:58	435	1305	
6 —	Field Blank —	1						
7 —	Field Blank —	1						
8 —	S. Blank —	1						

COMMENTS:

SAMPLE BY: Vyky Bedin. DATE: 11-18-02.

SIGNATURE: Yusef Bedier

RELEASED BY: Murray Bedwin. DATE: 1-18-02.

SIGNATURE: Wm. J. Baker Released - 12:05 PM

RECEIVED BY: A. G. 716AL DATE: 11/19/62

SIGNATURE: [Signature]

680-11-701

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION


ATHENICA

ENVIRONMENTAL SERVICES INC.

TEL (718) 784-7400

FAX (718) 784-4065

CLIENT: Warren & Panzer Engineers, P.C.

LABORATORY ID #: T02-11-091

ANALYT. METHODOLOGY: AHERA

FILTER TYPE: M.C.E.

 AVERAGE G.O. AREA (mm²): 0.013433

PROJECT: NYC DEP, 29 Park Row NY

DATE OF REPORT: 11/20/02

DATE OF ANALYSIS: 11/20/02

 EFFECTIVE FILTER AREA (mm²): 385

AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY

LABORATORY RESULTS

CLIENT #	LAB. ID #	LOCATION	VOLUME (l)	G.O.'s ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITIVITY (structured/cm ²)	TOTAL ASBESTOS AIR CONC. (fibre/cm ³)	TOTAL ASBESTOS FILTER CONC. (air/mm ²)	AIR CONC. FOR STRUCT. 0.55-5.0um	AIR CONC. FOR STRUCT. >5.0um	ASBEST. TYPE CHRYS.	AMPHIB. ASBEST. TYPE SPECIFY
01IWA	T02-11-091-4166	IWA on roof center of work area	1440	4	0.0537	0.0050	<0.0050	<18.6f	NA	NA	NA	NA
02IWA	T02-11-091-4167	IWA on roof north section of work area	1440	4	0.0537	0.0050	<0.0050	<18.6f	NA	NA	NA	NA
03IWA	T02-11-091-4168	IWA on roof south section of work area	1440	4	0.0537	0.0050	0.0050	18.6f	0.0050	<0.0050	Chrys.	NA
04IWA	T02-11-091-4169	IWA on roof 8Rt away of roof door entrance	1440	4	0.0537	0.0050	<0.0050	<18.6f	NA	NA	NA	NA
05OWA	T02-11-091-4170	OWA on stairwell leading to roof entrance 1ft of door entrance	1440	4	0.0537	0.0050	<0.0050	<18.6f	NA	NA	NA	NA

 ANALYST
E. Sioukri

 LABORATORY DIRECTOR
Spiro Dongaris

LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955

- Athenica Environmental Services Inc. (AES) is responsible only for information pertaining to samples taken by its employees.
- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc. did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.



ATHENICA
ENVIRONMENTAL SERVICES INC.

Tel. (718) 794-7490
Fax. (718) 794-4665

AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY

CLIENT: Warren & Panzer Engineers, P.C.

LABORATORY ID #: T02-11-096

ANALYT. METHODOLOGY: AHERA

FILTER TYPE: M.C.E.

AVERAGE G.O. AREA (mm²): 0.013433

PROJECT: NYC DEP, 29 Park Row

DATE OF REPORT: 11/21/02

DATE OF ANALYSIS: 11/21/02

EFFECTIVE FILTER AREA (mm²): 385

LABORATORY RESULTS

CLIENT #	LAB. ID #	LOCATION	VOLUME (l)	G.O. ANALYZED	AREA ANALYZED (m ²)	ANALYT. SENSITV. (struct/cm ³)	TOTAL ASBESTOS AIR CONC. (struct/cm ³)	TOTAL ASBESTOS FILTER CONC. (ctr./mm ²)	AIR CONC. FOR STRUCT. 0.5-5.0µm	AIR CONC. FOR STRUCT. >5.0µm	ASBEST. TYPE CHRYS.	AMPHIB. ASBEST. TYPE SPECIFY
01TWA	T02-11-096-4191	TWA on roof center of W/A	1320	5	0.0672	0.0043	<0.0043	<14.89	NA	NA	NA	NA
02TWA	T02-11-096-4192	TWA on roof north west section of W/A	1320	5	0.0672	0.0043	<0.0043	<14.89	NA	NA	NA	NA
03TWA	T02-11-096-4193	TWA on roof south east section of W/A	1320	5	0.0672	0.0043	<0.0043	<14.89	NA	NA	NA	NA
04TWA	T02-11-096-4194	TWA on roof 6ft of door entrance to roof	1320	5	0.0672	0.0043	0.0087	29.78	0.00887	<0.0043	Chrys.	NA
05OWA	T02-11-096-4205	OWA on stair well leading to roof door entrance	1320	5	0.0672	0.0043	<0.0043	<14.89	NA	NA	NA	NA

E. Sioultri

ANALYST
E. Sioultri

Sam P. Dossaris

LABORATORY DIRECTOR
Spiro Dossaris

LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955

- Athenica Environmental Services Inc. (AES), is responsible only for information pertaining to samples taken by its employees.
- Air sampling canisters will be sealed for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported asbestos concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

SEE REVERSE SIDE FOR ANALYSIS INFORMATION

TEL:

Jan 15, 01

14:47 No.001 P.15

AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY**ATHENICA**

ENVIRONMENTAL SERVICES INC.

Tel. (718) 794-7490

Fax. (718) 794-4085

CLIENT: Warren & Panzer Engineers, P.C.

LABORATORY ID #: T02-11-108

ANALYT. METHODOLOGY: AHERA

FILTER TYPE: M.C.E.

AVERAGE G.O. AREA (mm²): 0.013433

PROJECT: NYC DEP, 29 Park Row

DATE OF REPORT: 11/23/02

DATE OF ANALYSIS: 11/23/02

EFFECTIVE FILTER AREA (mm²): 385**LABORATORY RESULTS**

CLIENT #	LAB. ID #	LOCATION	VOLUME (ft ³)	G.O.'s ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITIV. (microg/cm ²)	TOTAL ASBESTOS AIR CONC. (microg/cm ³)	TOTAL ASBESTOS FILTER CONC. (microg/cm ²)	AIR CONC. FOR STRUCT. 0.553-5.5mm	AIR CONC. FOR STRUCT. 5.5-9.0um	ASBEST. TYPE CHRYS.	AMPHIB. ASBEST. TYPE SPECIFY
01	T02-11-108-4249	By the entrance	1500	4	0.0537	0.0048	<0.0048	<18.61	NA	NA	NA	NA
02	T02-11-108-4250	Inside work area south	1500	4	0.0537	0.0048	<0.0048	<18.61	NA	NA	NA	NA
03	T02-11-108-4251	Inside work area east	1500	4	0.0537	0.0048	<0.0048	<18.61	NA	NA	NA	NA
04	T02-11-108-4252	Inside work area west	1500	4	0.0537	0.0048	<0.0048	<18.61	NA	NA	NA	NA
05	T02-11-108-4253	Inside work area north	1500	4	0.0537	0.0048	0.0048	18.61	0.0048	<0.0048	Chrys.	NA

ANALYST
E. Sioukri

LABORATORY DIRECTOR
Spiro Dongaris**LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955**

- Athenica Environmental Services Inc. (AES) is responsible only for information pertaining to samples taken by its employees.
- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc. did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

TEL :

Jan 15.01

14:47 No.001 P.17

**ATHENICA**

ENVIRONMENTAL SERVICES INC.

Tel. (718) 764-7430

Fax. (718) 764-4035

AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY

CLIENT: Warner & Panzer Engineers, P.C.

LABORATORY ID #: T02-11-107

ANALYT. METHODOLOGY: AHERA

FILTER TYPE: M.C.E.

AVERAGE G.O. AREA (mm²): 0.013433

PROJECT: NYC DEP, 29 Park Row

DATE OF REPORT: 11/23/02

DATE OF ANALYSIS: 11/23/02

EFFECTIVE FILTER AREA (mm²): 385**LABORATORY RESULTS**

CLIENT #	LAB ID #	LOCATION	VOLUME (ft ³)	G.O. % ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITIV. (attomol/cm ³)	TOTAL ASBESTOS AIR CONC. (attomol/cm ³)	TOTAL ASBESTOS FILTER CONC. (attomol/cm ²)	AIR CONC. FOR STRUCT. 0.558-0.641	AIR CONC. FOR STRUCT. 0.641-0.925	ASBEST. TYPE CHRYA	ANALYT. TYPE SPECIFY
01	T02-11-107-4244	By the entrance	1440	4	0.0537	0.0050	0.0050	18.61	0.0050	<0.0050	Chrya	NA
02	T02-11-107-4245	Inside work area south	1440	4	0.0537	0.0050	<0.0050	<18.61	NA	NA	NA	NA
03	T02-11-107-4246	Inside work area east	1440	4	0.0537	0.0050	<0.0050	<18.61	NA	NA	NA	NA
04	T02-11-107-4247	Inside work area west	1440	4	0.0537	0.0050	<0.0050	<18.61	NA	NA	NA	NA
05	T02-11-107-4248	Inside work area north	1440	4	0.0537	0.0050	<0.0050	18.61	NA	NA	NA	NA

ANALYST
E. StoufferLABORATORY DIRECTOR
Spiro Dongaris**LABORATORY CERTIFICATION NUMBERS: NVLAP 101938, ELAP 10955**

- Athenica Environmental Services Inc. (AES), is responsible only for information pertaining to samples taken by its employees.
- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of this invoice.

OFF REVERSE SIDE FOR ANALYSIS INFORMATION

SIGNATURE: [Signature]

NYC-WTC_000115548

Asbestos Inspection Report

Premise No. 29 PARK ROW					Inspection Date: AS NOTED	
Floor ROOF & FACADE	Zip 10038	Borough 1	Block 90	Lot 10	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type COMMERCIAL		Basis of Inspection WTC Survey		Photos Taken Yes/No ☒ No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: AS NOTED		

MONDAY NOVEMBER 18 2002 TO TUESDAY NOVEMBER 19 2002

THE CLEAN UP OF THE ROOF OF THE PREMISE WAS CONDUCTED. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY YURI BEDIN (CERTIFICATE # AH 96-1494T EXP 02/03) OF WARREN & PANZER ENGINEERS. AIR SAMPLING EQUIPMENT WAS SET UP ON THE ROOF IN AN AREA OUTSIDE THE "ACTIVE CLEAN UP" AREA (IE. SAMPLING EQUIPMENT SET UP OF THE WESTERN HALF OF THE ROOF FOR THE CLEAN UP OF THE EASTERN HALF OF THE ROOF). DUE TO SPACE LIMITATIONS WORKERS WORE DOUBLE PROTECTIVE SUITS AND UTILIZED STEP OFF PADS IN LIEU OF REMOTE DECONTAMINATION FACILITIES. AT THE CONCLUSION OF THE CLEAN UP ACTIVITIES A VISUAL INSPECTION WAS CONDUCTED BY YURI BEDIN, NO VISIBLE WTC DEBRIS WAS OBSERVED.

THURSDAY NOVEMBER 21 2002 (0700AM - 1200 NOON)

HANGING SCAFFOLD WAS ERECTED ON THE WEST FACADE OF THE PREMISE. DUE TO LARGE CRACKS IN THE BUILDING'S FACADE SURFACES, CRACKED WINDOWS, LOOSE CORNICES AND COPING STONES, MODIFIED CLEAN UP PROCEDURES WILL BE EMPLOYED. BUILDING FACADE SURFACES WILL BE HEPA VACUUMED AND WET WIPED ONLY. POWER WASHING OF THE FACADE SURFACES WILL NOT BE DONE. A REASONABLE ATTEMPT WILL BE MADE TO ACCESS DEBRIS LODGED IN THE DAMAGED BUILDING FACADE SURFACES.

FRIDAY NOVEMBER 22 2002 (0700AM - 0700PM)

THE CLEAN UP OF THE WEST AND EAST FACADES OF THE PREMISE WAS CONDUCTED. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY CELESTINE NMORHA (CERTIFICATE # AH 02-08495 EXP 04/03) OF WARREN & PANZER ENGINEERS. AIR SAMPLING EQUIPMENT WAS SET UP ON THE WESTERN SECTION OF THE ROOF FOR THE WEST FACADE CLEAN UP AND ON THE

Asbestos Inspection Report

Premise No. <u>29 PARK ROW</u>	Inspection Date: <u>AS NOTED</u>
Inspector <u>Dennis Antzoulatos</u>	Page <u>2</u> of <u>2</u>
FRIDAY NOVEMBER 22 2002 (CONTINUED) EASTERN SECTION OF THE ROOF FOR THE EAST FACADE CLEAN UP. AT THE CONCLUSION OF THE CLEAN UP ACTIVITIES I CONDUCTED A VISUAL INSPECTION OF THE CLEANED SURFACES. A FINE FILM REMAINED IN THE CRACKS AND CREVICES OF ROUGH SURFACES. THIS FILM CAUSED A STREAKING APPEARANCE ESPECIALLY ON THE PAINTED SURFACES. REASONABLE ATTEMPTS WERE MADE TO SCRUB THE FILM OFF WITH TOWELS AND RAGS. THE FILM COULD NOT BE REMOVED WITHOUT POWER WASHING. DUE TO THE CONDITION OF THE BUILDING FACADES (CRACKS, BREAKS, ETC) POWER-WASHING WAS NOT AVAILABLE AS AN OPTION. UNDER THESE CIRCUMSTANCES, I WAS SATISFIED THAT THIS WAS THE BEST CLEAN UP THAT COULD BE PERFORMED. THE CLEAN UP PROJECT AT THE PREMISE IS NOW COMPLETE.	