

WTC Visual Survey Form

53 *Park*

Premise Address: 60 Marney / 153 Park Place 12 floors

Block: ☐ Residential ☒ Commercial ☐ Mix Use ☐ Other ☐ Name of Building: _____

Lot: _____

of Stories: 12 AKA's: _____

Building Owner/Management: _____ Telephone Number: () _____

Name: _____ FAX: () _____

Address: _____

On Site Contact: Security Super 233 6027

Name: PICARE FRAYNE Telephone Number: () 233 7941

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☐ No

Exterior Survey Performed ☐ Yes ☐ No

General Clean Up ☐ Yes ☐ No Locations: _____

ACM Clean Up ☐ Yes ☐ No Locations: _____

Air Monitoring ☐ Yes ☐ No Locations: _____

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

	Inspected	Debris
North ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
South ☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer ☒ 1/2 to 1" ☐ > 1"
East ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
West ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"

Facade Description: minor window etc

Roof

Debris: ☒ No Visible /Fine Layer light dust ☐ 1/2 to 1" 2 dust ☐ > 1" 1 dust

Description: 1

Setbacks ☐ N/A DUSTY PARK PLACE

Floor: _____	Debris: ☐ No Visible/Fine Layer ☒ 1/2 to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"

Comments Removal of 7 floors above foot, window boards

up

Date: 01 / 27 / 2002

Inspection Team: Name: AL

Name: UPPER

Agency: _____

Agency: _____

WTC Visual Survey Form

Premise Address: <u>Park Place / 50 Murray</u>		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Name:		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:		
North	☐ N/A	Inspected ☐ Yes ☐ No
South	☐ N/A	☐ Yes ☐ No
East	☐ N/A	☐ Yes ☐ No
West	☐ N/A	☐ Yes ☐ No
Debris		
☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"		
☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"		
☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"		
☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"		
Facade Description: <u>broken windows etc</u>		
Roof		
Debris: ☐ No Visible /Fine Layer ☒ 1/2 to 1" ☐ > 1"		
Description: <u>light dust INSPECTED FROM S3</u>		
Setbacks N/A ☐		
DIRTY		
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Comments <u>RENOVATIONS INTERNAL NO ACCESS TO ROOF</u>		
<u>UNKNOWN DEBRIS BOARDED IN?</u>		

Date: 01/27/2002

Inspection Team: Name: AC

Name: HENDERSON

Agency: _____

Agency: _____