

WTC Visual Survey Form

Premise Address: <i>43 Park Place</i>		
Block:	Residential ☐ Commercial ☒	Name of Building: <i>Burlington Coat Factory</i>
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Name:		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <i>Could not inspect all of facade from roof</i>					
Roof					
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description: <i>Construction debris also on roof.</i>					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Comments <i>Accessed for roof of 43 Park Place</i>					

Date: *5/28* /2002

ENTERED

Inspection Team: Name: *CTR*

Name: _____

Agency: _____

Agency: _____

WTC Visual Survey Form

Premise Address: <u>45 Park Pl</u>		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's: <u>49-51 Park Pl</u>	
Building Owner/Management:		Telephone Number: ()
Name: <u>Howard Walzman</u>		FAX: ()
Address: <u>85 E. End Ave NYC 10028</u>		
On Site Contact:		Telephone Number: ()
Name:		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <u>Dirty</u>					
Roof					
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description: <u>Dirty</u>					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 8/1/02 2002Inspection Team: Name: AL

Agency: _____

Name: _____

Agency: _____

ENTERED

WTC Visual Survey Form

Premise Address: 45 Park Place		
Block: 126	Residential ☐ Commercial ☒ Mix Use ☐ Other ☐	Name of Building:
Lot:		
# of Stories: 5	AKA's: BURUNSTON CORP	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No		Locations: _____
ACM Clean Up ☐ Yes ☐ No		Locations: _____
Air Monitoring ☐ Yes ☐ No		Locations: _____
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: broken windows etc					
Roof					
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" of dust ☐ > 1" of dust					
Description: INSPECTED FROM 53 PARK PL					
Setbacks N/A ☒					
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Comments					
NO ACCESS					

Date: 01/27/2002

Inspection Team: Name: AL

Name: MICHAEL R

Agency: _____

Agency: _____

WTC Visual Survey Form

Premise Address: <u>60 MERRAES / 53 PARK PLACE 12 floors</u>		
Block: <u>126</u>	Residential ☐ Commercial ☒	Name of Building:
Lot: <u>13</u>	Mix Use ☐ Other ☐	
# of Stories: <u>12</u>	AKA's: <u>41 West Broadway</u>	
Building Owner/Management Name:		Telephone Number: ()
		FAX: ()
Address:		
On Site Contact: <u>SCOTT</u>		
Name: <u>PICARE FRAYNE</u>		Telephone Number: () <u>233 6027</u>
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	☐ Yes ☐ No	Debris	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer ☒ ½ to 1" ☐ > 1"	
East	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	
West	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	
Facade Description: <u>minor windows etc</u>					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: <u>light dust</u>					
Setbacks <u>N/A</u> ☐ <u>DIVY PARK PLACE</u>					
Floor: _____	Debris:	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Comments <u>Removal of 7 floors above roof, window boards</u>					
<u>up</u>					

Date: 01 / 27 / 2002Inspection Team: Name: AL

Agency: _____

Name: UPNETS

Agency: _____

WTC Visual Survey Form

Premise Address:			<i>PARK PLACE @ 53+45</i>		
Block:	Residential ☐ Commercial ☒	Name of Building:			
Lot:	Mix Use ☐ Other ☐				
# of Stories: <i>5</i>	AKA's: <i>BURLINGTON COAL FACTORY</i>				
Building Owner/Management:			Telephone Number: ()		
Name:			FAX: ()		
Address:					
On Site Contact:					
Name:			Telephone Number: ()		
Building Owner Management Activities					
Interior Survey Performed ☐ Yes ☐ No					
Exterior Survey Performed ☐ Yes ☐ No					
General Clean Up ☐ Yes ☐ No Locations: _____					
ACM Clean Up ☐ Yes ☐ No Locations: _____					
Air Monitoring ☐ Yes ☐ No Locations: _____					
Copies of All Reports and Data Requested ☐ Yes					

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <i>Brick windows etc.</i>					
Roof					
Debris: ☐ No Visible /Fine Layer <i>light dust</i> ☒ ½ to 1" of dust ☐ > 1" of dust.					
Description: <i>INSPECTED FROM 53 PARK PL</i>					
Setbacks N/A ☐					
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Comments					

Date: *01 / 27 / 2002*Inspection Team: Name: *AL*

Agency: _____

Name: *PERINER*

Agency: _____