

WTC Visual Survey Form

Premise Address: <u>43 Parole PL</u>		
Block: <u>126</u>	Residential ☐ Commercial ☒ Mix Use ☐ Other ☐	Name of Building:
Lot: <u>8</u>		
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name: <u>Key PK Place Corp</u>		FAX: ()
Address: <u>65 Roosevelt Ave Valley Stream N.Y 11581</u>		
On Site Contact:		Telephone Number: ()
Name:		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <u>Dirty</u>					
Roof					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: <u>Dirty</u>					
Setbacks ☐ N/A					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 8/17/2002Inspection Team: Name: AL

Agency: _____

Name: _____ Agency: _____