

ASBESTOS INSPECTION REPORT

EMISE NO.		STREET				INSPECTION DATE	
43 Park		PLACE				10/1/02	
DOOR	ZIP	BORO CODE	BLOCK	LOT	SQUAD #	BADGE #	
AF	10007	1	126	8	1	AD10	
SPECTOR		BLDG TYPE	BASIS OF INSPECT.			PHOTOS TAKEN YES (NO)	
J. P. HANSON		PLUMBER	WTC SURVEY			YES (NO)	
CONTRACTORS NAME				SAMPLE NO.			
FIBER CONTROL				SAMPLE NO.			
ADDRESS				CITY			
3010 BURNS AVE				WANTAGH			
STATE	ZIP	PHONE	SAMPLE NO.				
N.Y.	11793	(516) 781-3000	SAMPLE NO.				
LABORATORY NAME				OWNERS NAME			
WARREN & PANZER ENGINEERS, PC				Key Park Place Corp			
ADDRESS				CITY			
228 E. 45TH ST				N.Y.			
STATE	ZIP	PHONE	STATE		ZIP	PHONE	
N.Y.	10017	(212) 922-0077	N.Y.		11581		
CONTACT PERSON:				TIME OF INSPECTION FROM: 3:00 pm TO: 8:00 pm			
INSPECTION DISCLOSED:							

The roof and the facade was cleaned except the facade of the first floor area. The tenant who is the owner of Dakota Roadhouse requested that the Air Condition unit and the entire entrance be plasticized. The entire area was plasticized and the upper area facade and roof were cleaned.

No visible debris observed after the cleaning.

NOV #	INFRACTIONS					RESULT CODE
						5
NOV #						SUPERVISORS INITIALS
						PL

BORO 1 - MANHATTAN 2 - BRONX 3 - BROOKLYN 4 - QUEENS 5 - RICHMOND

BLDG TYPE A > 6 Stories B < 6 Stories C Single Family
D School E Hospital F Public Owned Property

RESULT CODES 1 - Violation Issued 2 - No Violations Issued 3 - No Access
4 - Project not Started (No NOV) 5 - Project Completed (No NOV)

ACP 309

FILE