

WTC Visual Survey Form

Premise Address: <u>17 Park Place</u>		
Block:	Residential ☒ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories: <u>5</u>	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name: <u>United American Land</u>		FAX: ()
Address: <u>Jodie Habase</u>		
On Site Contact:		Telephone Number: ()
Name:		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description:

Broken windows etc

Roof

Debris:

☐ No Visible /Fine Layer☐ ½ to 1" of dust☐ > 1" of dust.

Description:

no accessSetbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 1/27 /2002

Inspection Team: Name:

Bob Fitzpatrick

Agency:

KEPA

Name:

Penny Redorelly

Agency:

NYC DEP

RF-9

Page: 1 Document Name: Extra

01/30/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPIQ31
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
17..... PARK PLACE..... 1 MANHATTAN 10007 BIN# 1001400
DCP GEOGRAPHICAL INFORMATION:
PARK PLACE 17 - 17 HEALTH AREA : 77 TAX BLK: 124..
MURRAY STREET 14 - 14 CENSUS TRACT: 1009 TAX LOT: 7....
COMMUNITY BD: 101 CONDO :
MULTI STRUCT: 1 CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : AZTEC ASSOCIATES AZTEC ASSOCIATES
CORP. NAME : LPC LANDMARK STATUS: NO
ADDRESS : 430 W BROADWAY DOB LOCAL LAW STATUS: YES
NEW YORK NY 10012-3784
DOF BUILDING INFORMATION: TRANS LAND VALUE: 1,620,000
BLDG SIZE; 0026.00 X 0152.00 TAX EXEMPT FLAG : NO
LOT SIZE: 0025.58 X 0151.83 TAX EXEMPT CLASS:
BLDG CLASS : K9 STORE BUILDING CITY OWNERSHIP : NO
STORIES : 5 UPDATE DATE : 01/12/02
FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:
OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

Date: 1/30/ 2 Time: 12:13:10 PM



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

EL758387582US

February 12, 2002

Aztec Associates
430 West Broadway
New York, NY 10012-3784

Subject: 17 PARK PLACE
14 Murray St

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

A handwritten signature in dark ink, appearing to read "R. Radhakrishnan".

R. Radhakrishnan, P.E.
Director

Asbestos Control Program



www.nyc.gov/dep

(718) DEP-HELP



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

Aztec Associates
430 West Broadway
New York, NY 10012-3784

**Subject: 17 PARK PLACE
14 Murray St
Second Notice**

February 23, 2002


Dear Sir/ Madam:

This is a follow-up to the NYC DEP request for copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. To date, our office has not received the requested documents and information. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,


R. Radhakrishnan, P.E.
Director
Asbestos Control Program



www.nyc.gov/dep

(718) DEP-HELP