

WTC Visual Survey Form

Prerise Address: 102 North End Ave		
Block: Lot:	Residential ☐ Commercial ☒ Mix Use ☐ Other ☐	Name of Building: Embassy Hotel
# of Stories: 15	AKA's:	
Building Owner/Management: Name: S		Telephone Number: () FAX: ()
Address:		
On Site Contact: Name: Lubomir Cuba - Supervisor		Telephone Number: (718) 531-2900
Building Owner Management Activities		
Interior Survey Performed	☒ Yes ☐ No	All Testing Stillman Environmental - Mike Ucc - Samples also An Schaefer Copies of All Reports and Data Requested ☐ Yes
Exterior Survey Performed	☒ Yes ☐ No	
General Clean Up	☐ Yes ☐ No	
ACM Clean Up	☒ Yes ☐ No	
Air Monitoring	☒ Yes ☐ No	
Locations:		
Locations:		
Locations:		

Visual Inspection Results:

Facade:			
North	☐ N/A	Inspected	Debris
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Facade Description: Facades to be cleaned again.			
Roof			
Debris: ☒ No Visible /Fine Layer ☐ 1/2 to 1" ☒ > 1"			
Description: To be rectified again.			
Setbacks N/A ☐			
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"		
Comments 25 Room as Alberto's Property 4/1 handover on site Working on 2nd floor + Benjamin Kutzman - Clean Up Contractor			

Date: 1/27/2002

Inspection Team: Name: CTR L
Name: _____Agency: DCP
Agency: _____

