

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 212-290-0058 Email:

EMSL

Attn: U.S. EPA - Residential
HQ Financial Services Division
1200 Pennsylvania Ave, NW Maildrop 2734R
Washington, DC 20460

Customer ID: USEPA44
Customer PO: 2W-1103-NNLX
Received: 12/13/01 2:05 PM

Fax: Phone:
Project: USPHS Mission #12 Residential Sampling New York
City Bldg 6,7,12-23,26,29,31-34

EMSL Order: 030109702
EMSL Project ID:
Analysis Date: 12/14/01

450 North End Ave

**Asbestos Analysis of Non-Friable Organically Bound materials by Transmission
Electron Microscopy via NYS ELAP Method 198.4**

SAMPLE ID	DESCRIPTION	APPEARANCE	MATRIX MATERIAL	NON-ASBESTOS FIBERS	ASBESTOS TYPES	TOTAL ASBESTOS
[R]VA-R1-14 030109702-0012	RESIDENCE 1		100.0	None	No Asbestos Detected	
[R]VA-R2-14 030109702-0013	RESIDENCE 2		100.0	None	No Asbestos Detected	
[R]SA-O-13 030109702-0014	OUTDOORS	Roof Sample (debris in between crack of tile)	98.1	None	1.9 Chrysotile	1.9
[R]VA-C-15 030109702-0015	COMMON AREA		100.0	None	No Asbestos Detected	
[R]VA-R1-15 030109702-0016	RESIDENCE 1		100.0	None	<1 Chrysotile	<1
[R]VA-R2-15 030109702-0017	RESIDENCE 2		100.0	None	No Asbestos Detected	
[R]VA-C-16 030109702-0018	COMMON AREA		100.0	None	No Asbestos Detected	
[R]VA-R2-16 030109702-0019	RESIDENCE 2		100.0	None	No Asbestos Detected	
[R]SA-O-16 030109702-0020	OUTDOORS		100.0	None	No Asbestos Detected	
[R]VA-C-17 030109702-0021	COMMON AREA		100.0	None	No Asbestos Detected	
[R]VA-R1-17 030109702-0022	RESIDENCE 1		100.0	None	No Asbestos Detected	

Analyst

Eric B. B.
Laboratory Manager
or other approved signatory

This laboratory is not responsible for % asbestos in total sample when the residue only is submitted for analysis. This above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc.
ACCREDITATIONS: NALAP #1010-069 and NY STATE ELAP #11905

NY 108-