

Asbestos Inspection Report

FINAL

Premise No. 35 ANN STREET					Inspection Date: 06-23-02	
Floor ROOF	Zip	Borough 1	Block 92	Lot 23	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type COMMERCIAL		Basis of Inspection WTC Survey		Photos Taken Yes ☒ No ☐
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: 7 ⁰⁰ AM - 3 ⁰⁰ PM		

7:00AM	I REQUEST AND I AM PRESENTED WITH VALID NYC DEP AND NYS DOL ASBESTOS HANDLER/ SUPERVISOR CERTIFICATES FOR ALL WORKERS INVOLVED AT THE JOBSITE.
8:00AM	WORKERS BEGIN SETTING UP OF PLASTIC DYKE TO COLLECT ANY RUN-OFF WATER FROM THE FACADE CLEAN UP OF THIS PREMISE.
8:35AM	FILTRATION SYSTEM FOR THE RUN-OFF WATER IS IN PLACE.
9:25AM - 10:15AM	WARREN & PANZER REPRESENTATIVE BEGINS AIR SAMPLING FOR THIS PROJECT. FOR THE PURPOSES OF AIR SAMPLING THE FACADE OF 35 ANN STREET AND 45 ANN STREET WILL BE CONSIDERED ONE WORK AREA. FIVE AIR SAMPLES COLLECTIVELY ARE RUN FOR THESE TWO WORK AREAS. LOCATIONS ARE AS FOLLOWS: 1 @ DECON UNIT, 2 ON THE SIDE WALK JUST OUTSIDE THE WORK AREA AND 2 ON THE ROOF OF 45 ANN (MID).
	W&P REP: LARRY BAEZ FLOW RATE: 3 LITERS/MIN.
12:00PM	WORKERS HAVE COMPLETED THE FACADE CLEAN UP OF 35 ANN STREET. A VISUAL INSPECTION WILL BE CONDUCTED WHEN THE FACADE IS COMPLETELY DRY.
3:00PM	I CONDUCT A VISUAL INSPECTION OF THE FACADE OF 35 ANN STREET. WORK AREA IS FOUND TO BE CLEAN. VISUAL INSPECTION IS PASSED. BOTH FACADE AND ROOF AREAS HAVE BEEN CLEANED. THE PROJECT IS NOW COMPLETED.