

ASBESTOS INSPECTION REPORT

PAGE 1 OF

PREMISE ADDRESS 106 Liberty Street (AKA) 111 Cedar Street					INSPECTION DATE 8/04/02 & 8/05/02	
FLOOR Roof & Facade	ZIP 10006	BORO CODE 1	BLOCK	LOT	SQUAD 1	BADGE # AO78
INSPECTOR R. RAMMOHAN		BLDG. TYPE B	BASIS OF INSPECTION TRU1204MN02			PHOTOS TAKEN YES
CONTRACTORS NAME Trio Asbestos Removal Corp.				SAMPLE NO. -----		
ADDRESS 14-20 th Street College Point				SAMPLE NO. -----		
STATE ZIP PHONE NY 11356 (718) 961-4100				SAMPLE NO. -----		
LABORATORY NAME Warren & Panzer Engineers, P.C.				OWNERS NAME 111 Cedar Street Co. C/O Sylven Lawrence		
ADDRESS 228 East 45 th Street New York				ADDRESS 100 William Street New York		
STATE ZIP PHONE NY 10017 (212) 922-0077				STATE ZIP PHONE NY (212) 344-0044		
CONTACT PERSON Joe Bonder				TIME OF INSPECTION FROM: 8 am – 8 pm		
INSPECTION DISCLOSED: 8/03/02: Saturday: Handler Supervisor Sasa Simic and 6 handlers and the Air-sampling Technician John Boyd came on site. Crew set-up dykes on cedar street, Trinity Place and Liberty street. Crew of four started on the roof cleaning A/C units & Donnage. At the end of the day crew completed the roof. Air monitoring was performed throughout the clean-up. 8/04/02: Sunday: Handler Supervisor Sasa Simic and seven Handlers started to set-up dykes on Trinity Place, Cedar Street and Liberty Street sidewalks for facades cleaning. The boom truck was moved to Liberty Street and façade cleaning started after setting-up dykes with plastic on the scaffolding bridge. A second crew comprising Supervisor Jan Wolkowicz and six handlers started cleaning the façade under the bridge. The Air monitoring was performed by Ellis of Warren & Panzer. The façade on Liberty Street was completed. Sasa and crew started cleaning the façade of Cedar Street using the boom truck. Cleaning complete at 2:00 pm visual inspection was satisfactory. The boom truck was moved to 113-117 Cedar Street to clean the three rows of windows from west side, that was over sprayed by the crew at 114 Cedar Street. Crew also cleaned the Granite façade face of 113-117 Cedar Street. All cleaning completed and the crew left the site after cleaning all three sidewalks.						
NOV #	INFRACTIONS					RESULT CODE 5
NOV #						SUPERVISORS INITIALS slp

BORO 1=MANHATTAN 2=BRONX 3=BROOKLYN 4=QUEENS 5=STATEN ISLAND

BLDG. TYPE A > 6 STORIES B < 6 STORIES C SINGLE FAMILY
D SCHOOL E HOSPITAL F PUBLIC OWNED PROPERTYRESULT CODES 1 = Violation Issued 2 = No Violation Issued 3 = No access
4 = Project not Started (no NOV) 5 = Public Owned Property

ACP3093

ASBESTOS INSPECTION REPORT

PAGE 1 OF

PREMISE ADDRESS 106 Liberty Street (AKA) 111 Cedar Street					INSPECTION DATE 8/04/02 & 8/05/02	
FLOOR Roof & Facade	ZIP 10006	BORO CODE 1	BLOCK	LOT	SQUAD 1	BADGE # AO78
INSPECTOR R. RAMMOHAN		BLDG. TYPE B	BASIS OF INSPECTION TRU1204MN02			PHOTOS TAKEN YES
CONTRACTOR'S NAME Trio Asbestos Removal Corp.				SAMPLE NO. -----		
ADDRESS 14-20, 120 th Street College Point				SAMPLE NO. -----		
STATE ZIP PHONE NY 11356 (718) 961-4100				SAMPLE NO. -----		
LABORATORY NAME Warren & Panzer Engineers, P.C.				OWNER'S NAME 111 Cedar Street Co. C/O Sylven Lawrence		
ADDRESS 228 East 45 th Street New York				ADDRESS 100 William Street New York		
STATE ZIP PHONE NY 10017 (212) 922-0077				STATE ZIP PHONE NY (212) 344-0044		
CONTACT PERSON Joe Bonder				TIME OF INSPECTION FROM: 8 am - 8 pm		
INSPECTION DISCLOSED: 8/03/02: Saturday: Handler Supervisor Sasa Simic and 6 handlers and the Air-sampling Technician John Boyd came on site. Crew set-up dykes on cedar street, Trinity Place and Liberty street. Crew of four started on the roof cleaning A/C units & Donnage. At the end of the day crew completed the roof. Air monitoring was performed throughout the clean-up. 8/04/02: Sunday: Handler Supervisor Sasa Simic and seven Handlers started to set-up dykes on Trinity Place, Cedar Street and Liberty Street sidewalks for facades cleaning. The boom truck was moved to Liberty Street and facade cleaning started after setting-up dykes with plastic on the scaffolding bridge. A second crew comprising Supervisor Jan Wolkowicz and six handlers started cleaning the facade under the bridge. The Air monitoring was performed by Ellis of Warren & Panzer. The facade on Liberty Street was completed. Sasa and crew started cleaning the facade of Cedar Street using the boom truck. Cleaning complete at 2:00 pm visual inspection was satisfactory. The boom truck was moved to 113-117 Cedar Street to clean the three rows of windows from west side, that was over sprayed by the crew at 114 Cedar Street. Crew also cleaned the Granite facade face of 113-117 Cedar Street. All cleaning completed and the crew left the site after cleaning all three sidewalks.						
NOV #	INFRACTIONS					RESULT CODE 5
NOV #						SUPERVISORS INITIALS

BORO 1=MANHATTAN 2=BRONX 3=BROOKLYN 4=QUEENS 5=STATEN ISLAND

BLDG. TYPE A > 6 STORIES B < 6 STORIES C SINGLE FAMILY
D SCHOOL E HOSPITAL F PUBLIC OWNED PROPERTY
RESULT CODES 1 = Violation Issued 2 = No Violation Issued 3 = No access
4 = Project not Started (no NOV) 5 = Public Owned Property

ACP3093

ASBESTOS INSPECTION REPORT

PAGE 1 OF

PREMISE ADDRESS 106 Liberty Street (AKA) 111 Cedar Street					INSPECTION DATE 8/04/02 & 8/05/02	
FLOOR Roof&Facade	ZIP 10006	BORO CODE 1	BLOCK	LOT	SQUAD 1	BADGE # AO78
INSPECTOR R. RAMMOHAN		BLDG. TYPE B	BASIS OF INSPECTION TRU1204MN02			PHOTOS TAKEN YES
CONTRACTOR'S NAME Trio Asbestos Removal Corp.				SAMPLE NO.-----		
ADDRESS 14-20, 120 th Street College Point				SAMPLE NO.-----		
STATE ZIP PHONE NY 11356 (718) 961-4100				SAMPLE NO.-----		
LABORATORY NAME Warren & Panzer Engineers, P.C.				OWNER'S NAME 111 Cedar Street Co. C/O Sylven Lawrence		
ADDRESS 228 East 45 th Street New York				ADDRESS 100 William Street New York		
STATE ZIP PHONE NY 10017 (212) 922-0077				STATE ZIP PHONE NY (212) 344-0044		
CONTACT PERSON Joe Bonder				TIME OF INSPECTION FROM: 8 am - 8 pm		
INSPECTION DISCLOSED: 8/03/02: Saturday: Handler Supervisor Sasa Simic and 6 handlers and the Air-sampling Technician John Boyd came on site. Crew set-up dykes on cedar street, Trinity Place and Liberty street. Crew of four started on the roof cleaning A/C units & Donnage. At the end of the day crew completed the roof. Air monitoring was performed throughout the clean-up. 8/04/02: Sunday: Handler Supervisor Sasa Simic and seven Handlers started to set-up dykes on Trinity Place, Cedar Street and Liberty Street sidewalks for facades cleaning. The boom truck was moved to Liberty Street and façade cleaning started after setting-up dykes with plastic on the scaffolding bridge. A second crew comprising Supervisor Jan Wolkowicz and six handlers started cleaning the façade under the bridge. The Air monitoring was performed by Ellis of Warren & Panzer. The façade on Liberty Street was completed. Sasa and crew started cleaning the façade of Cedar Street using the boom truck. Cleaning complete at 2:00 pm visual inspection was satisfactory. The boom truck was moved to 113-117 Cedar Street to clean the three rows of windows from west side, that was over sprayed by the crew at 114 Cedar Street. Crew also cleaned the Granite façade face of 113-117 Cedar Street. All cleaning completed and the crew left the site after cleaning all three sidewalks.						
NOV #	INFRACTIONS					RESULT CODE 5
NOV #						SUPERVISORS INITIALS

BORO 1=MANHATTAN 2=BRONX 3=BROOKLYN 4=QUEENS 5=STATEN ISLAND

BLDG. TYPE A > 6 STORIES B < 6 STORIES C SINGLE FAMILY
D SCHOOL E HOSPITAL F PUBLIC OWNED PROPERTYRESULT CODES 1 = Violation Issued 2 = No Violation Issued 3 = No access
4 = Project not Started (no NOV) 5 = Public Owned Property

ACP3093