

WTC Visual Survey Form

1000041

Premise Address: <u>11 Stone St</u>		
Block: <u>11</u> Lot: <u>29</u>	Residential ☐ Commercial ☐ Mix Use ☐ Other ☐	Name of Building:
# of Stories:	AKA's:	
Building Owner/Management: Name:		Telephone Number: () FAX: ()
Address:		
On Site Contact: Name: <u>Mario</u>		Telephone Number: ()
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:		
North ☐ N/A South ☐ N/A East ☐ N/A West ☐ N/A	Inspected ☒ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	Debris ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☒ > 1" ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1" ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1" ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Facade Description: _____		
Roof		
Debris: ☒ No Visible /Fine Layer ☐ 1/2 to 1" ☐ > 1"		
Description: _____		
Setbacks N/A ☐		
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Comments		

Date: 4/12/2002

Inspection Team: Name: _____

Agency: _____

Name: _____

Agency: _____

ENTERED



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of Air, Noise, &
Hazardous Materials**

Tel (718) 595-4418
Fax (718) 595-4422

April 12, 2002

Building Owner Name: _____

Address: 11 Stone St

NYC

Subject: Memo to (Super)

Dear Sir/Madam:

In September 2001, the New York City Department of Environmental Protection (NYCDEP) and the Department of Health (NYCDOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the assessment of building contamination for possible hazardous components, including asbestos.

Today, a visual survey of your building's exterior was conducted as a follow up to DEP's October survey of buildings around the World Trade Center site. At the above referenced site, visible dust accumulations were observed at:

- ☒ building facade(s)
- ☐ setback(s)
- ☐ roof
- ☐ other, _____

Please be advised building owners are responsible for the cleaning of building exteriors, grounds and common areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

Please provide information regarding your actions to address the dust accumulations by April 25, 2002. Copies of the environmental hazard assessments including bulk sample results, air monitoring results and/or a summary of clean-up activities at the above-referenced site may be faxed to (718) 595-3744 or sent to the NYCDEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

If you have any questions, you may reach the NYCDEP at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. NYCDEP staff is available to provide guidance and technical assistance.

Sincerely,

for A
R. Radhakrishnan, P.E.
Director
Asbestos Control Program



www.ci.nyc.ny.us/dep

(718) DEP-HELP

04/16/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPI031
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
11..... STONE STREET..... 1 MANHATTAN 10004 BIN# 1000041
DCP GEOGRAPHICAL INFORMATION:
STONE STREET 11 - 13 HEALTH AREA : 77 TAX BLK: 11...
CENSUS TRACT: 2002 TAX LOT: 29...
COMMUNITY BD: 101 CONDO :
MULTI STRUCT: 1 CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : LMS REALTY LLC LMS REALTY LLC
CORP. NAME : LPC LANDMARK STATUS: NO
ADDRESS : 227 E 56TH ST DOB LOCAL LAW STATUS: YES
NEW YORK NY 10022-3751
DOF BUILDING INFORMATION: TRANS LAND VALUE: 1,000,000
BLDG SIZE: 0044.00 X 0083.00 TAX EXEMPT FLAG : NO
LOT SIZE: 0044.17 X 0083.17 TAX EXEMPT CLASS:
BLDG CLASS : 09 OFFICE BUILDING CITY OWNERSHIP : NO
STORIES : 5 UPDATE DATE : 03/25/02
FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:
OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

NYC DEP

59-17 Junction Blvd.
 Corona, NY 11368
 (718)DEP-HELP Fax (718)595-4096

Service Request Inspection Detail

Report Date 03/14/2002 02:47 PM

Submitted By

Page 2

Linked Requests

Service #	Problem	Problem Date	Address
Location			

No Linked Requests for this Service Request Inspection

NYC DEP

Method

Source

Critical Service

Log Log Type Comments	Description	Log Started	Log Ended	Entered By
-----------------------------	-------------	-------------	-----------	------------

There are no log entries for this service number

End of Report