

WTC Visual Survey Form

TRINITY (Hatch
Managers)

Premise Address: 74 TRINITY PLACE		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories: 26	AKA's:	
Building Owner/Management:		Telephone Number: (212) 602 0761
Name: Mica Bohrer		FAX: ()
Address: same		
On Site Contact:		Telephone Number: ()
Name: same		
Building Owner Management Activities Interior Survey Performed ☒ Yes ☐ No Exterior Survey Performed ☒ Yes ☐ No General Clean Up ☒ Yes ☐ No Locations: Negative Result ACM Clean Up ☐ Yes ☐ No Locations: Air Monitoring ☒ Yes ☐ No Locations:		
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: **Facade Power washed**

Roof

Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"

Description: **X**

Setbacks

N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

All HVAC was cleaned & tested
Filter changed

Date: **1/25** /2002Inspection Team: Name: **CARL**

Name: _____

Agency: **DGP**

Agency: _____

DIN 100102

WTC Visual Survey Form

BIN 1001231

Premise Address:

74 Trinity Place / 209-21 Broadway

Block:

Residential ☐

Commercial ☐

Name of Building:

Lot:

Mix Use ☐

Other ☒ Church

St. Paul's

of Stories:

AKA's:

Building Owner/Management:

Telephone Number: ()

Name:

LARO

FAX: ()

Address:

240 Madison Ave., NY, NY.

On Site Contact:

Name:

Peter SAGLIUCCA Facility Mgr. Telephone Number: (212) 571-4352

Building Owner Management Activities

Interior Survey Performed ☒ Yes ☐ No ?

Exterior Survey Performed ☒ Yes ☐ No

General Clean Up ☒ Yes ☐ No

Locations: MAXON - Inside & Outside

ACM Clean Up ☐ Yes ☒ No

Locations:

Air Monitoring ☒ Yes ☐ No

Locations:

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

North ☐ N/A

Inspected

☒ Yes ☐ No

South ☐ N/A

☒ Yes ☐ No

East ☐ N/A

☒ Yes ☐ No

West ☐ N/A

☒ Yes ☐ No

Debris

☒ No Visible/Fine Layer

☐ 1/2 to 1"

☐ > 1"

☒ No Visible/Fine Layer

☐ 1/2 to 1"

☐ > 1"

☒ No Visible/Fine Layer

☐ 1/2 to 1"

☐ > 1"

☒ No Visible/Fine Layer

☐ 1/2 to 1"

☐ > 1"

Facade Description:

Brick windows etc

Roof

Debris:

☒ No Visible/Fine Layer

☐ 1/2 to 1" dust

☐ > 1" dust

Description:

Small amounts of debris in gutter. Pitched roof very clean.

Setbacks

N/A ☒

Floor: _____

Debris: ☐ No Visible/Fine Layer

☐ 1/2 to 1"

☐ > 1"

Floor: _____

Debris: ☐ No Visible/Fine Layer

☐ 1/2 to 1"

☐ > 1"

Floor: _____

Debris: ☐ No Visible/Fine Layer

☐ 1/2 to 1"

☐ > 1"

Floor: _____

Debris: ☐ No Visible/Fine Layer

☐ 1/2 to 1"

☐ > 1"

Floor: _____

Debris: ☐ No Visible/Fine Layer

☐ 1/2 to 1"

☐ > 1"

Comments

FBI did clean up of the yard. Court/grave

Court yard/graveyard highly contaminated with WTC debris. Owner should have debris tested.

Date: 1/28/2002

Inspection Team: Name: A. Fitzpatrick

Agency: USEPA

Name: _____

Agency: _____