

WTC Visual Survey Form

Premise Address: 89 Broadway		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☒ Church	TRINITY Church
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: (212) 602 0761
Name: Mike Bonero		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Name: Porter		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: Info Not Available		
ACM Clean Up ☐ Yes ☐ No Locations:		
Air Monitoring ☐ Yes ☐ No Locations:		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	Debris	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: Porter					
Roof					
Debris: ☒ No Visible /Fine Layer ^{light dust} ☐ ½ to 1" ☐ > 1" ^{1 dust}					
Description: Very Sloped Roof					
Setbacks N/A ☒					
Floor: _____	Debris: ☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					
Adjacent Lot is free of debris					

Date: 1/24/2002

Inspection Team: Name:

CARL LUTCHMEYER

Agency:

DCV

Name:

Agency:

WTC Visual Survey Form

TRINITY (Hitch Manager)

Premise Address: 74 TRINITY PLACE		
Block: Lot:	Residential ☐ Commercial ☒ Mix Use ☐ Other ☐	Name of Building:
# of Stories: 26	AKA's:	
Building Owner/Management: Name: Mica Bohrer		Telephone Number: (214) 602 0761 FAX: ()
Address: same		
On Site Contact: Name: same		Telephone Number: ()
Building Owner Management Activities Interior Survey Performed ☒ Yes ☐ No Exterior Survey Performed ☒ Yes ☐ No General Clean Up ☒ Yes ☐ No Locations: Negative Result ACM Clean Up ☐ Yes ☐ No Locations: Air Monitoring ☒ Yes ☐ No Locations: Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:			
North ☐ N/A	Inspected ☐ Yes ☐ No	Debris ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	
South ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	
East ☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	
West ☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	
Facade Description: Facade Power washed			
Roof			
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"			
Description:			
Setbacks N/A ☐			
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"		
Comments: All HVAC was cleaned + tested Filter changed			

Date: **1/25/2002**Inspection Team: Name: **CARL**
Name:Agency: **DCP**
Agency: