

NOT IN THE
LIST

86 86 **WTC Visual Survey Form** ?

Premise Address: 89 TRINITY PLACE

Block: Residential ☐ Commercial ☒ **Name of Building:** American Stock Exchange

Lot: Mix Use ☐ Other ☐

of Stories: 15 **AKA's:**

Building Owner/Management: Name: Carol Hoover UP (AMEX) Telephone Number: (212) 306 1180
FAX: ()

Address: 86 Trinity Place

On Site Contact: Name: Thomas S. Sacharewitz Telephone Number: (212) 306 1663

Building Owner Management Activities

Interior Survey Performed ☒ Yes ☐ No
Exterior Survey Performed ☒ Yes ☐ No
General Clean Up ☒ Yes ☐ No Locations: _____
ACM Clean Up ☐ Yes ☒ No Locations: _____
Air Monitoring ☒ Yes ☐ No Locations: _____

Copies of All Reports and Data Requested ☒ Yes

Visual Inspection Results:**Facade:**

		Inspected	Debris		
North	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: grainy windows etc.**Roof**

Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" of dust ☒ > 1" of dust.

Description: To test and clean

Setbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 1/25/2002

Inspection Team: Name: Carol L. IntermecineAgency: DEP

Name: _____

Agency: _____