

Page: 1 Document Name: Extra

01/30/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPIQ31
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
100..... TRINITY PLACE..... 1 MANHATTAN 10006 BIN# 1001037
DCP GEOGRAPHICAL INFORMATION:
TRINITY PLACE 96 - 102 HEALTH AREA : 77 TAX BLK: 52...
CEDAR STREET 108 - 118 CENSUS TRACT: 2002 TAX LOT: 1....
THAMES STREET 13 - 19 COMMUNITY BD: 101 CONDO :
MULTI STRUCT: 1 CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : NEW YORK UNIVERSITY NEW YORK UNIVERSITY
CORP. NAME : LPC LANDMARK STATUS: NO
ADDRESS : 838 BROADWAY DOB LOCAL LAW STATUS: NO
NEW YORK NY 10003-4812
DOF BUILDING INFORMATION: TRANS LAND VALUE: 11,500,000
BLDG SIZE: 0099.00 X 0170.00 TAX EXEMPT FLAG : YES
LOT SIZE: 0102.42 X 0127.50 TAX EXEMPT CLASS: X7
BLDG CLASS : W6 EDUCATIONAL STRUCTURES CITY OWNERSHIP : NO
STORIES : 0 UPDATE DATE : 01/12/02
FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:
OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

Date: 1/30/ 2 Time: 08:29:16 AM

WTC Visual Survey Form

Premise Address: 100 TRINITY PL ?

Block: Residential ☐ Commercial ☐ **Name of Building:** SCHOOL

Lot: Mix Use ☐ Other ☐

of Stories: 10 **AKA's:**

Building Owner/Management: Alex Lemper SCA **Telephone Number:** ()

Name: Alex **FAX:** ()

Address:

On Site Contact: Alex **Telephone Number:** ()

Building Owner Management Activities

Interior Survey Performed ☒ Yes ☐ No

Exterior Survey Performed ☒ Yes ☐ No

General Clean Up ☒ Yes ☐ No **Locations:** _____

ACM Clean Up ☐ Yes ☒ No **Locations:** _____

Air Monitoring ☒ Yes ☐ No **Locations:** _____

Copies of All Reports and Data Requested ☒ Yes

Visual Inspection Results:

Facade:

	Inspected	Debris
North	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
South	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
East	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
West	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"

Facade Description: z

Roof

Debris: ☐ No Visible /Fine Layer ☒ 1/2 to 1" ☐ > 1"

Description: Small accumulations on North Side.

Setbacks N/A ☐

Floor:	Debris:
_____	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
_____	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
_____	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
_____	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
_____	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"

Comments

Date: 1/25/2002

Inspection Team: Name: CAP

Name:

Agency: DCP

Agency: