

WTC Visual Survey Form

Premise Address: 100 TRINITY Place		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☒ School	HS of Economics & Finance
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Name: Mohammed / Alex Kemp		
Building Owner Management Activities		
Interior Survey Performed	☒ Yes ☐ No	
Exterior Survey Performed	☒ Yes ☐ No	
General Clean Up	☒ Yes ☐ No	Locations: _____
ACM Clean Up	☒ Yes ☐ No	Locations: _____
Air Monitoring	☒ Yes ☐ No	Locations: _____
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: _____

Roof

Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"

Description: _____

Setbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 2/28/2002

Inspection by: Name: _____

Agency: _____

Name: _____

Agency: _____

WTC Visual Survey Form

Premise Address: 100 TRINITY PL		
Block: 52	Residential ☐ Commercial ☐ Mix Use ☐ Other ☐	Name of Building: SCHOOL
Lot: 1		
# of Stories: 10	AKA's: 91 Trinity	
Building Owner/Management Name: Alex Lemper SCA		Telephone Number: ()
		FAX: ()
Address:		
On Site Contact Name: Alex		Telephone Number: ()
Building Owner Management Activities Interior Survey Performed ☒ Yes ☐ No Exterior Survey Performed ☒ Yes ☐ No General Clean Up ☒ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☒ No Locations: _____ Air Monitoring ☒ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:				
North	☒ N/A	Inspected ☒ Yes ☐ No	Debris ☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	
South	☒ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	
East	☒ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	
West	☒ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	
Facade Description: 2				
Roof				
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"				
Description: Small accumulations on North Side.				
Setbacks N/A ☐				
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"			
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"			
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"			
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"			
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"			
Comments				

Date: 1/25/2002

Inspection Team: Name: CAP

Name:

Agency: DCP

Agency: