

WTC Visual Survey Form

Premise Address: 100 TRINITY PL		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐	SCHOOL
# of Stories: 10	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name: Alex Lemper SC A		FAX: ()
Address:		
On Site Contact:		
Name: Alex		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☒ Yes ☐ No		
Exterior Survey Performed ☒ Yes ☐ No		
General Clean Up ☒ Yes ☐ No		Locations: _____
ACM Clean Up ☐ Yes ☒ No		Locations: _____
Air Monitoring ☒ Yes ☐ No		Locations: _____
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:					
North	☒ N/A	Inspected	☒ Yes ☐ No	Debris	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
South	☒ N/A	☒ Yes ☐ No	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	☐ > 1"
East	☒ N/A	☒ Yes ☐ No	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	☐ > 1"
West	☒ N/A	☒ Yes ☐ No	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"	☐ > 1"
Facade Description: <i>z</i>					
Roof					
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description: <i>Small accumulations on North Side.</i>					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"				
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"				
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"				
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"				
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"				
Comments					

Date: 1/12/2002

Inspection Team: Name: *CAF*
Name: _____Agency: *DCT*
Agency: _____