

WTC Visual Survey Form

1066414

Premise Address: 58 Thomas St		
Block: 197	Residential ☒ Commercial ☐	Name of Building:
Lot: 24	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management: 58 Thomas Condo		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	Debris	☒ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"	
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"	
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"	
Facade Description: _____					
Roof					
Debris: ☒ No Visible / Fine Layer ☐ 1/2 to 1" ☐ > 1"					
Description: _____					
Setbacks N/A ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Comments					
major Renovation taking place.					

Date: 4/13/2002

Inspection Team: Name: RAM & SHAN

Agency: DEP.

Name: _____ Agency: _____

ENTERED



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

April 13, 2002

Building Owner Name: 58 THOMAS ST. Bldg Owner
Address: 58 THOMAS ST.
MANH.
Subject: 58 THOMAS ST.

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

Deesh Foz

**R. Radhakrishnan, P.E.
Director
Asbestos Control Program**



www.nyc.gov/dep

(718) DEP-HELP

Page: 1 Document Name: Extra

04/15/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPIQ31
 MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
 58..... THOMAS STREET..... 1 MANHATTAN 10013 BIN# 1066414
 DCP GEOGRAPHICAL INFORMATION:
 THOMAS STREET 58 - 58 HEALTH AREA : 77 TAX BLK: 147..
 CENSUS TRACT: 2010 TAX LOT: 24...
 COMMUNITY BD: 101 CONDO :
 MULTI STRUCT: 1 CUI NO :
 DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
 OWNER NAME : 58 THOMAS ST ASSOCIATES LLC 58 THOMAS ST ASSOCIAT
 CORP. NAME : LPC LANDMARK STATUS: LANDMARK
 ADDRESS : 145 HUDSON ST DOB LOCAL LAW STATUS: NO
 NEW YORK NY 10013-2103
 DOF BUILDING INFORMATION: TRANS LAND VALUE: 408,000
 BLDG SIZE: 0024.83 X 0100.00 TAX EXEMPT FLAG : NO
 LOT SIZE: 0024.83 X 0100.58 TAX EXEMPT CLASS:
 BLDG CLASS : Z9 MISCELLANEOUS CITY OWNERSHIP : NO
 STORIES : 1 UPDATE DATE : 03/25/02
 FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:
 OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

 PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

Date: 4/15/ 2 Time: 12:18:40 PM

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Inspection Detail

Report Date 04/11/2002 11:02 AM

Submitted By

Page 2

NYC DEP

Method

Source

Critical Service

**Log
Log Type
Comments**

Description

Log Started

Log Ended

Entered By

There are no log entries for this service number

End of Report