

WTC Visual Survey Form

1000847

✓

Premise Address: 21-23 South William St

Block: 29 **Residential** ☐ **Commercial** ☒ **Name of Building:**

Lot: 49 **Mix Use** ☐ **Other** ☒ LANDMARK

of Stories: **AKA's:**

Building Owner/Management: **Telephone Number:** ()

Name: **FAX:** ()

Address:

On Site Contact: **Telephone Number:** ()

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☐ No

Exterior Survey Performed ☐ Yes ☐ No

General Clean Up ☐ Yes ☐ No **Locations:** _____

ACM Clean Up ☐ Yes ☐ No **Locations:** _____

Air Monitoring ☐ Yes ☐ No **Locations:** _____

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☒ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☒ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☒ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☒ > 1"

Facade Description: broken windows etc ...

Roof

Debris: ☐ No Visible /Fine Layer ^{light dust} ☐ ½ to 1" of dust ☒ > 1" of dust.

Description: _____

Setbacks N/A ☒

Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"

Comments Extensive renovations going on in the external and interior of bldg.

Date: 4/19/2002
ENTERED

Inspection Team: Name: AL Agency: _____
Name: _____ Agency: _____



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of Air, Noise, &
Hazardous Materials**

Tel (718) 595-4418
Fax (718) 595-4422

April 19, 2002

Building Owner Name: _____

Address: _____

21-23 South Williams St
NYC

Subject: _____

Dear Sir/Madam:

In September 2001, the New York City Department of Environmental Protection (NYCDEP) and the Department of Health (NYCDOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the assessment of building contamination for possible hazardous components, including asbestos.

Today, a visual survey of your building's exterior was conducted as a follow up to DEP's October survey of buildings around the World Trade Center site. At the above referenced site, visible dust accumulations were observed at:

- ☒ building facade(s)
- ☐ setback(s)
- ☒ roof
- ☐ other, _____

Please be advised building owners are responsible for the cleaning of building exteriors, grounds and common areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

Please provide information regarding your actions to address the dust accumulations by April 25, 2002. Copies of the environmental hazard assessments including bulk sample results, air monitoring results and/or a summary of clean-up activities at the above-referenced site may be faxed to (718) 595-3744 or sent to the NYCDEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

If you have any questions, you may reach the NYCDEP at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. NYCDEP staff is available to provide guidance and technical assistance.

Sincerely,

**R. Radhakrishnan, P.E.
Director
Asbestos Control Program**



www.ci.nyc.ny.us/dep

(718) DEP-HELP



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Mile Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

April 19, 2002

Building Owner Name: _____

Address:

21-23 South Williams St
NYC

Subject: _____

Dear Sir/ Madam:


In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,


R. Radhakrishnan, P.E.
Director
Asbestos Control Program



www.nyc.gov/dep

(718) DEP-HELP

Page: 1 Document Name: Extra

```

04/22/02          N.Y.C. DEPARTMENT OF BUILDINGS          BISPI031
          MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
21..... SOUTH WILLIAM STREET..... 1 MANHATTAN          10004 BIN# 1000847
DCP GEOGRAPHICAL INFORMATION:
SOUTH WILLIAM STREET 21 - 23          HEALTH AREA : 77          TAX BLK: 29...
STONE STREET          45 - 47          CENSUS TRACT: 1004          TAX LOT: 49...
          COMMUNITY BD: 101          CONDO :
          MULTI STRUCT: 1          CUI NO :

DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : BLOCK HALL DEVELOPMENT CO LLC          BLOCK HALL DEVELOPMEN
CORP. NAME :          LPC LANDMARK STATUS: LANDMARK
ADDRESS : 26          BROADWAY          DOB LOCAL LAW STATUS: YES
          NEW YORK NY 10004-1756

DOF BUILDING INFORMATION:          TRANS LAND VALUE: 1,000,000
BLDG SIZE: 0048.00 X 0083.00          TAX EXEMPT FLAG : NO
LOT SIZE: 0051.00 X 0083.67          TAX EXEMPT CLASS:
BLDG CLASS : K9 STORE BUILDING          CITY OWNERSHIP : NO
STORIES : 7          UPDATE DATE : 03/25/02
FOR CITY } MGMT TYPE:          MGMT CODE:          MGMT CODE NAME:
OWNERSHIP }          MGMT HOLDER CODE:          MGMT HOLDER CODE NAME:
-----
PF1 =PREV  PF2 =MAIN  PF7 = NEW ADDRESS  PF8 = NEW BLK/LOT  PF9 = NEW BIN

```

Date: 4/22/ 2 Time: 02:08:20 PM