

1079058

WTC Visual Survey Form

Premise Address: <u>80 South Street</u>		
Block: <u>72</u>	Residential ☐ Commercial ☒	Name of Building:
Lot: <u>31</u>	Mix Use ☐ Other ☐	
# of Stories:	AKA's: <u>78-80 SOUTH ST. 44 FLETCHER ST / 82 SOUTH ST.</u>	
Building Owner/Management Name:		Telephone Number: () <u>83 South St.</u>
		FAX: ()
Address:		
On Site Contact:		
Name: <u>Vine</u>		Telephone Number: ()
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☒ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☒ Yes ☐ No	☒ Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description:

Brick

Roof

 Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"
 Description: No access
Setbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

ledge & windows have visible fine layer of dustNO ACCESSDate: 4/20/2002Inspection Team: Name: Lisa
Name: _____Agency: NYC DEP.
Agency: _____

ENTERED



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

April 13
~~February~~, 2002

Building Owner Name: *Acme Construction*

Address: _____

Subject: *80 South Street*

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan
R. Radhakrishnan, P.E.
Director
Asbestos Control Program



Page: 1 Document Name: Extra

```

04/24/02          N.Y.C. DEPARTMENT OF BUILDINGS          BISPI031
          MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
78..... SOUTH STREET..... 1 MANHATTAN          10038 BIN# 1079058
DCP GEOGRAPHICAL INFORMATION:
SOUTH STREET          78 - 80          HEALTH AREA : 77          TAX BLK: 72...
FLETCHER STREET      44 - 44          CENSUS TRACT: 21009          TAX LOT: 31...
SOUTH STREET          83 - 83          COMMUNITY BD: 101          CONDO :
SOUTH STREET          82 - 82          MULTI STRUCT: 2          CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : 80 SOUTH ST LLC          80 SOUTH ST LLC
CORP. NAME : SCIAME          LPC LANDMARK STATUS: NO
ADDRESS : 80 SOUTH ST          DOB LOCAL LAW STATUS: NO
          NEW YORK NY 10038-4970
DOF BUILDING INFORMATION:
BLDG SIZE: 0096.00 X 0117.00          TRANS LAND VALUE: 3,200,000
LOT SIZE: 0096.67 X 0118.00          TAX EXEMPT FLAG : NO
BLDG CLASS : 01 OFFICE BUILDING          TAX EXEMPT CLASS:
STORIES : 6          CITY OWNERSHIP : NO
FOR CITY } MGMT TYPE:          MGMT CODE:          UPDATE DATE : 03/25/02
OWNERSHIP } MGMT HOLDER CODE:          MGMT CODE NAME:
          MGMT HOLDER CODE NAME:
-----
PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

```

Date: 4/24/ 2 Time: 03:56:31 PM