

69 South St.

1081994

16 STRUCTURES: 1903812 WTC Visual Survey Form

Premise Address: <u>16 Fulton St</u>		
Block: <u>74</u>	Residential ☐ Commercial ☐	Name of Building:
Lot: <u>1</u>	Mix Use ☐ Other ☒ <u>LANDMARK</u>	
# of Stories:	AKA's: <u>14-18 FULTON ST. 197 FRONT ST. 195 FRONT ST 193</u>	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Name: <u>None</u>		
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:		
	Inspected	Debris
North	☐ N/A ☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
South	☐ N/A ☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
East	☒ N/A ☐ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
West	☐ N/A ☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Facade Description: <u>Red brick, no visible debris, stores in ground floor</u>		
Roof		
Debris: ☒ No Visible /Fine Layer ☐ 1/2 to 1" ☐ > 1"		
Description: <u>Sloped roof inspected east side roof. No visible debris on west side roof.</u>		
Setbacks N/A ☐		
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Comments: <u>Left letter on the door</u>		

Date: ____/____/2002
ENTERED

Inspection Team: Name: A. Regan Agency: OPC DEP
Name: J. Nelson Agency: 4



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

April 13,
February _____, 2002

Building Owner Name: _____

Address: _____

Subject: 16 Fulton Street

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan
R. Radhakrishnan, P.E.
Director
Asbestos Control Program



04/25/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPI031
 MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
 14..... FULTON STREET..... 1 MANHATTAN 10038 BIN# 1081994
 DCP GEOGRAPHICAL INFORMATION:
 FULTON STREET 14 - 18 HEALTH AREA : 77 TAX BLK: 74...
 FRONT STREET 197 - 197 CENSUS TRACT: 21008 TAX LOT: 1....
 FRONT STREET 195 - 195 COMMUNITY BD: 101 CONDO :
 FRONT STREET 193 - 193 MULTI STRUCT: 16 CUI NO :
 DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
 OWNER NAME : SCIAM DEVELOPMENT IN SCIAM DEVELOPMENT IN
 CORP. NAME : LPC LANDMARK STATUS: NO
 ADDRESS : SOUTH STREET DOB LOCAL LAW STATUS: NO
 NEW YORK NY 10038
 DOF BUILDING INFORMATION:
 BLDG SIZE: ** UNKNOWN ** TRANS LAND VALUE: 0
 LOT SIZE: ** UNKNOWN ** TAX EXEMPT FLAG : NO
 BLDG CLASS : K9 STORE BUILDING TAX EXEMPT CLASS:
 STORIES : 0 CITY OWNERSHIP : YES
 FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:
 OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

 PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN