

WTC Visual Survey Form

Premise Address: <u>146 88 Greenwich St</u>		
Block: Lot:	Residential ☒ Commercial ☐ Mix Use ☐ Other ☐	Name of Building:
# of Stories: <u>37</u>	AKA's:	
Building Owner/Management: Name: <u>Sch O'Brien</u>		Telephone Number: <u>(212) 504 8817</u> FAX: ()
Address:		
On Site Contact: Name: <u>Security Officer</u>		Telephone Number: ()
Building Owner Management Activities Interior Survey Performed ☒ Yes ☐ No Exterior Survey Performed ☒ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☒ No Locations: _____ Air Monitoring ☒ Yes ☒ No Locations: _____ Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: _____

Roof

Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"

Description: Gravel Roof

Setbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 1/1/2002

Inspection Team: Name: Carol Hutchinson Agency: DHS
 Name: _____ Agency: _____