

***** -IND. XMT JOURNAL- ***** DATE DEC-04-2002 ***** TIME 12:47 *****

DATE/TIME = DEC-04-2002 12:46
 JOURNAL No. = 14
 COMM.RESULT = OK
 PAGE(S) = 001/001
 DURATION = 00:00'39
 FILE No. = 078
 MODE = MEMORY TRANSMISSION
 DESTINATION = 912122851818
 RECEIVED ID = /
 RESOLUTION = STD

-NYCDEP BANHM ASB/LEAD TRU-

***** -

- ***** - 718 595 3648- *****

9/18/01 80 Maiden Lane

North Atlantic Labs. (Floors: 3, 4, 5, 6, 7
8, 9, 10, 12, 13, 14, 15 & 19)

Total PCM Samples Collected = 41

Total positives = 1 (10th floor)

Total negatives = 40

71 Broadway

9/20/01

EM & CA Labs. (2nd floor)

PCM 2400 method

Total Samples = 2

Total negatives = 2

Total positives = 0

(Ground & 4th floors) 88 Greenwich 9/20/01
EM & CA LABS. PCM 2400 method

Total samples = 2

Total negatives = 2

Total positives = 0

WTC Visual Survey Form

Premise Address: <u>19 Redm St. Closed</u>		
Block:	Residential ☐ Commercial ☒	Name of Building: <u>Dinu</u>
Lot:	Mix Use ☐ Other ☐	
# of Stories: <u>25</u> AKA's: _____		
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address: _____		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: _____					
Roof					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: _____					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 1/26 /2002Inspection Team: Name: CARL
Name: _____Agency: DEP
Agency: _____