

WTC Visual Survey Form

Premise Address: 345 South End Ave

Block: Residential ☒ Commercial ☐ **Name of Building:**

Lot: Mix Use ☐ Other ☐

of Stories: AKA's: 345 South End Ave

Building Owner/Management: Telephone Number: ()

Name: Gateway Plaza FAX: ()

Address:

On Site Contact: Telephone Number: (212) 321-2500

Name: Mr. DeFrancesco

Building Owner Management Activities

Interior Survey Performed ☒ Yes ☐ No

Exterior Survey Performed ☒ Yes ☐ No

General Clean Up ☒ Yes ☐ No Locations: _____

ACM Clean Up ☐ Yes ☐ No Locations: _____

Air Monitoring ☐ Yes ☒ No Locations: _____

Copies of All Reports and Data Requested ☒ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: broken windows etc No visible debris

Roof

Debris: ☒ No Visible /Fine Layer ^{light dust} ☐ ½ to 1" ^{1 dust} ☒ > 1" ^{1 dust}

Description: Debris on the air ducts etc

Setbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments: All Envir. test did air monitoring

Date: ___/___/2002

Inspection Team: Name: AL

Name: Kolin

Agency: Del

Agency: Del

WTC Visual Survey Form

Premise Address: <u>395 South End Ave Bldg # 600</u>		
Block:	Residential ☒ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:

		Inspected		Debris				
North	☐ N/A	☒ Yes ☐ No		☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
South	☐ N/A	☒ Yes ☐ No		☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
East	☐ N/A	☒ Yes ☐ No		☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
West	☐ N/A	☒ Yes ☐ No		☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		

Facade Description: _____

Roof

Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"

Description: _____

Setbacks ☐ N/A

Floor: _____	Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"	Debris: ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"	Debris: ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"	Debris: ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"	Debris: ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"	Debris: ☐ > 1"

Comments

Date: 2/27/2002Inspection by: Name: RAMAgency: DEP

Name: _____ Agency: _____

375 South End Avenue

Roof Mechanical Exhaust Fan #8 Roof Mechanical Exhaust Fan #16	For Each: Components and ducts
Basement Compactor Room Exhaust and Intake	Components and ducts
Basement CVD24 Exhaust	Components and ducts
Basement Gym Exhaust	Components and ducts